

General Environmental Incident Summary

Incident: 3540 **Date/Time Notice:** 11/7/2014 12:20 **DEM Incident No:**

Responsible Party: Hess Bakken Investments II LLC

Date Incident: 11/7/2014 **Time Incident:** 12:20 **Duration:**

County: Mountrail **Twp:** 155 **Rng:** 93 **Sec:** 30 **Qtr:**

Lat: 48.21394 **Long:** -102.68490 **Method:** Interpolation from map

Location Description: Hess Bakken Investments II, LLC
En Abrahamson 155-93-3019 H-5
Intersection of 55 ST NW / Hwy 1804, travel west approx. 3.5 miles location
is on the north side of Hwy 1804

Submitted By: Troy Brunsell **Affiliation:**

Address: 3015 16TH ST SW, Suite 20

City: Minot **State:** ND **Zip:**

Received By:

Contact Person:

3015 16TH ST SW, Suite 20
Minot, ND

Distance Nearest Occupied Building: 0.5 Miles **Release Contained:** Yes

Type of Incident: Tank Leak

Description of Released Contaminant: #5 Burner Spec Oil (PUMO)

Volume Spilled: 80.00 barrels **Ag Related:** No

EPA Extremely Hazardous Substance: No **Reported to NRC:** No

Cause of Incident:

Contract hauler was in the process of re-fueling water heating truck, upon completion of re-fueling the operator drove away with hose still connected breaking the line causing #5 Burner Spec Oil (PUMO) to leak out onto the ground migrating to the NE corner of location entering the ditchline on the NE side.

Risk Evaluation:

No immediate risk, fluid is contained along location

of Fatalities: 0 **# of Injuries:** 0 **Affected Medium:** 03 - soil

Potential Environmental Impacts:

Soil / water in ditchline along location

Action Taken or Planned:

Berms were placed along the ditchline stopping the fluid from moving. Vac trucks were on location to vac up standing fluid. Cleanup crew will be dispatched to sample / cleanup any impacted material transporting to approved disposal with clean material put in its place.

Wastes Disposal Location: Approved disposal facility

Agencies Involved:

Updates

Date: 11/7/2014 **Status:** Reviewed - Follow-up Required

Author: Roberts, Kris

Updated Volume:

Notes:

11/7/14 - 10:40: While meeting Jason Henry of Hess on another location, I was informed of a used motor oil leak at the EN Abrahamson 155-93-3019 H-5 location. Used motor oil was being delivered for an on-site heating system, and hose was inadvertently pulled loose. Oil ran off location. Immediate off-site containment berming was initiated to stop further migration, and cleanup contractors have been mobilized. Followup is necessary.

Date: 4/24/2015 **Status:** Inspection

Author: Stockdill, Scott

Updated Volume:

Notes:

Arrived on location 2:01 4/7/2015.

No sign of spill at the time of inspection. An email has been sent to the responsible party requesting the results of the samples that were taken during the time of the cleanup.

More followup is necessary.

Date: 5/29/2015 **Status:** Awaiting Documentation

Author: Stockdill, Scott

Updated Volume:

Notes:

Sent email to company contact requesting information on the sampling that occurred.

More followup is necessary.