

General Environmental Incident Summary

Incident: 3600 **Date/Time Notice:** 1/7/2015 1215 **DEM Incident No:**
Responsible Party: MBI Energy Services
Date Incident: 1/6/2015 **Time Incident:** 1500 **Duration:** 5 minutes
County: Burke **Twp:** 162 **Rng:** 93 **Sec:** 4 **Qtr:**
Lat: 48.88745 **Long:** -102.74280 **Method:** Interpolation from map
Location Description: 2 Miles East of Columbus, ND at Basin Transload-Stampede Facility

Submitted By: Chad Miller **Affiliation:** MBI Environmental Manager
Address: 931 S 9th Street, Ste 201
City: Bismarck **State:** ND **Zip:** 58504

Received By:

Contact Person: Chad Miller
12980 35th Street Southwest
Belfield , ND 58662

Distance Nearest Occupied Building: 0.62 Miles **Release Contained:** No

Type of Incident: Pressure release from oil truck

Description of Released Contaminant: Crude Oil

Volume Spilled: 30.00 gallons **Ag Related:** No

EPA Extremely Hazardous Substance: No **Reported to NRC:** No

Cause of Incident:

The tank trailer is equipped with a vent line to balance pressure as oil is heated and cooled. Operational error caused the vent line to be closed, building pressure in the tank. When the vent line was opened, pressure push oil out in the form of a spray. The spray fell on to County Rd 7 and on to the adjacent ditch and upon snow.

Risk Evaluation:

None.

of Fatalities: 0 **# of Injuries:** 0 **Affected Medium:** 09 - other

Potential Environmental Impacts:

None - majority was on paved roadway and snow, which clean up took place immediately.

Action Taken or Planned:

Clean-up was completed by absorbing the oil off of the road and washing of residual. Contaminated snow in the ditch was scooped up.

Wastes Disposal Location: Recovered wastes will be brought to Chimney Butte or PDI.

Agencies Involved:

Updates

Date: 1/12/2015 **Status:** Reviewed - Follow-up Required

Author: Stockdill, Scott

Updated Volume:

Notes:

According to the incident summary, a majority of this spill remained on an impermeable surface. However, followup is necessary to ensure proper cleanup.

Date: 1/28/2015 **Status:** Inspection

Author: Suess, Bill

Updated Volume:

Notes:

Release was confined to the asphalt roadway and snow-covered shoulder. Absorbent material was placed on roadway and then scraped up. Impacted snow was removed. Material was hauled to PDI. No further action is warranted.