

General Environmental Incident Summary

Incident: 3636 **Date/Time Notice:** 2/3/2015 **DEM Incident No:**

Responsible Party: Randy Jones

Date Incident: 2/3/2015 **Time Incident:** **Duration:**

County: Dunn **Twp:** 147 **Rng:** 95 **Sec:** 27 **Qtr:**

Lat: 47.52099 **Long:** -102.76600 **Method:** Interpolation from map

Location Description: From Killdeer N on hwy 22 approximately 14mi. East on CCU Rd.

Submitted By: Randy Jones

Affiliation:

Address: Box 488

City: Killdeer

State: ND

Zip:

Received By:

Contact Person: Randy Jones
Box 488
Killdeer, ND

Distance Nearest Occupied Building:

Release Contained: No

Type of Incident: Vehicle Accident

Description of Released Contaminant: Crude Oil

Volume Spilled: 30.00 barrels

Ag Related: No

EPA Extremely Hazardous Substance: No

Reported to NRC: No

Cause of Incident:

Rolled vehicle in ditch. Punctured back of the trailer.

Risk Evaluation:

Soil contamination

of Fatalities:

of Injuries:

Affected Medium: 03 - soil

Potential Environmental Impacts:

Soil contamination

Action Taken or Planned:

Certified clean up crew arrived on location to remedy the spill. Soil samples will be taken and further cleanup will be conducted if necessary.

Wastes Disposal Location: Certified disposal facility

Agencies Involved:

Updates

Date: 2/3/2015 **Status:** Reviewed - Follow-up Required

Author: Espe, Brady

Updated Volume:

Notes:

Vehicle accident with crude oil spill into road ditch. Followup inspection is necessary.

Date: 2/4/2015 **Status:** Correspondence

Author: Martin, Russell

Updated Volume:

Notes:

Received phone call from responsible party's company, MBI. Company will be sampling site. Company rep requested that the initial response of "Unknown" to the line that reads "Reported to NRC" be switched to "No" since the release did not impact water. Additionally, PDI may be disposal location, but company is still investigating. Updated report to reflect change.

Date: 2/5/2015 **Status:** Correspondence

Author: Crowdus, Kory

Updated Volume:

Notes:

Received call from company contact at MBI. Contact requested that the report of release being contained be changed from "yes" to "no," as the spill entered the roadside ditch. I was also informed that the company did report spill to landowner and that contaminated material was taken to PDI for disposal.

Date: 2/12/2015 **Status:** Inspection

Author: Cooper, Mike

Updated Volume:

Notes:

Arrived on site. 15°F, wind 10-15 mph.

Directions to the site – turn east near mile marker 117.5, travel about 1.5 miles, and the location is on the left.

Excavation has been done. New soil has been brought in and covers the extent of the area.

Talked with site contact, and he gave me the information provided on the new directions to the site.

Disposal has been done, and further followup is needed to check for vegetative growth in the future.

Date: 9/1/2015 **Status:** Inspection

Author: Washek, Sandi

Updated Volume: 30.00 barrels

Notes:

Arrived on site at 6:28 p.m. Sunny, 88 degrees, wind from the west at 15 mph. Checked the area for vegetation growth in the ditch where the spill occurred. Had a hard time finding the site due to the good regrowth of the vegetation. No additional followup needed for this site.