

# General Environmental Incident Summary

**Incident:** 3693      **Date/Time Notice:** 3/25/2015      **DEM Incident No:**

**Responsible Party:** Northwest Colorado Transport

**Date Incident:** 3/24/2015      **Time Incident:** 0945      **Duration:**

**County:** Dunn      **Twp:** 145      **Rng:** 95      **Sec:** 23      **Qtr:**

**Lat:** 47.35828      **Long:** -102.73950      **Method:** Interpolation from map

**Location Description:** North side of the road on HWY 200, approximately 2 miles east of the Killdeer roundabout.

**Submitted By:** Cameron Keeney      **Affiliation:**

**Address:** 122 Central Ave.

**City:** killdeer      **State:** ND      **Zip:**

**Received By:**

**Contact Person:**

122 Central Ave.  
killdeer, ND

**Distance Nearest Occupied Building:**      **Release Contained:** Yes

**Type of Incident:** CMV lost its fuel tank while traveling west bound.

**Description of Released Contaminant:** Diesel fuel

**Volume Spilled:** 75.00 gallons      **Ag Related:** No

**EPA Extremely Hazardous Substance:** Unknown      **Reported to NRC:** Unknown

**Cause of Incident:**

The driver's side fuel tank of a CMV became loose and fell off while traveling west bound on HWY 200. Diesel fuel was released out of the fitting in the bottom of the tank that was knocked off after making contact with the road.

**Risk Evaluation:**

Substance that was released poses a fire hazard as it is a flammable liquid.

**# of Fatalities:**      **# of Injuries:**      **Affected Medium:** 03 - soil

**Potential Environmental Impacts:**

Potential to contaminate soil and rain water in

**Action Taken or Planned:**

The spill was immediately contained. A crew was dispatched to remediate the spill and remove all contaminated soil and replace the soil with new material.

**Wastes Disposal Location:**

**Agencies Involved:**

## **Updates**

---

**Date:** 3/25/2015    **Status:** Reviewed - Follow-up Required

**Author:** Roberts, Kris

**Updated Volume:**

**Notes:**

Vehicle accident on Hwy 200 east of Killdeer. Followup is necessary.

---

**Date:** 3/30/2015    **Status:** Inspection

**Author:** Espe, Brady

**Updated Volume:**

**Notes:**

I arrived at the site at 14:09 p.m. The weather is clear, 68°F, with the wind from the northwest at 10-15 mph. I talked to the contact. The tank was lost in the north ditch about 500 yards from tank battery and well site. On the south side of the highway is a shop building with trailers on east side of lot, and there is a row of pine trees to the west of shop along the south side of highway. The tank had been removed, and I did not see any stained areas in ditch. No further followup needed at this time. 38.8555; 94.79907