

# General Environmental Incident Summary

**Incident:** 3735      **Date/Time Notice:** 4/27/2015      1624      **DEM Incident No:**

**Responsible Party:** Kinder Morgan

**Date Incident:** 4/25/2015      **Time Incident:** 1145      **Duration:** 2 minutes

**County:** McKenzie      **Twp:** 152      **Rng:** 96      **Sec:** 20      **Qtr:** SE SE SE

**Lat:** 47.96385      **Long:** -102.98760      **Method:** Interpolation from map

**Location Description:** Rolfsrud State 152-96-29-32-2HZ, From the town of Keene, ND, at the junction of Hwy 23 and 1st Ave W, travel North on Hwy 23 for approx. 3.4 miles to the intersection of Hwy 23 and County Road 10. Turn left on County Road 10 and travel West for approx. 2.6 miles to the intersection of County Road 10 and 113th Ave NW. Turn left and travel South on 113th Ave NW for approx. 1.0 mile to the access road for the location on the left.

**Submitted By:** Tim Eaton

**Affiliation:**

**Address:** 363 N Sam Houston Pky E

Ste. 100

**City:** Houston

**State:** TX

**Zip:** 77060

## Received By:

**Contact Person:** Wade McDaniel  
1001 Louisiana St.  
Ste. 1000  
Houston, TX 77002

**Distance Nearest Occupied Building:**

**Release Contained:** Yes

**Type of Incident:** Pump Leak

**Description of Released Contaminant:** Diesel

**Volume Spilled:** 340.00 gallons

**Ag Related:** No

**EPA Extremely Hazardous Substance:** No

**Reported to NRC:** No

## Cause of Incident:

Fuel pump on generator blew a hole in the top of itself but was still able to run pumping fuel out into the housing which overflowed onto the ground. The secondary containment berm did not hold but all diesel remained on the well pad.

## Risk Evaluation:

Had the potential to ignite and possibly explode.

**# of Fatalities:** 0

**# of Injuries:** 0

**Affected Medium:** 03 - soil

## Potential Environmental Impacts:

Soil on well site was contaminated.

## Action Taken or Planned:

The diesel was contained to the active oil well site. The generator was shut down and all soil was excavated and replaced with clean fill dirt.

**Wastes Disposal Location:** Renewable Resources

**Agencies Involved:** NDIC

### **Updates**

---

**Date:** 4/27/2015    **Status:** Reviewed - Follow-up Required

**Author:** Martin, Russell

**Updated Volume:**

**Notes:**

Release, due to pump leak, stayed on location; however, substance is not E&P exempt. Followup is necessary.

---

**Date:** 4/29/2015    **Status:** Correspondence

**Author:** Espe, Brady

**Updated Volume:**

**Notes:**

Received call indicating that the report was not submitted correctly. Will be getting email on correct information.

---

**Date:** 4/30/2015    **Status:** Correspondence

**Author:** Martin, Russell

**Updated Volume:**

**Notes:**

According to representative for wellpad owner, impacted dirt has been removed from the site.

---

**Date:** 5/11/2015    **Status:** Reviewed - No Action Required

**Author:** Martin, Russell

**Updated Volume:**

**Notes:**

Release was contained on a wellpad. Amount released was below the reporting threshold for NDIC, so a report did not need to be filed. No followup required.