

# General Environmental Incident Summary

**Incident:** 3757      **Date/Time Notice:** 5/21/2015      0910      **DEM Incident No:**

**Responsible Party:** CHS INC.

**Date Incident:** 5/21/2015      **Time Incident:** 0800      **Duration:** 0.2 minutes

**County:** Morton      **Twp:** 139      **Rng:** 81      **Sec:** 30      **Qtr:**

**Lat:** 46.83076      **Long:** -100.95880      **Method:** Interpolation from map

**Location Description:** 2365 Business loop I94 Mandan ND 58554

**Submitted By:** Eric Pearson

**Affiliation:** CHS Inc

**Address:** 4155 27th Ave N

**City:** Grand Forks

**State:** ND

**Zip:** 58203

## Received By:

**Contact Person:** Eric Pearson  
4155 27th Ave N  
Grand Forks, ND 58203

**Distance Nearest Occupied Building:** 50 Feet      **Release Contained:** Yes

**Type of Incident:** Tank Overflow

**Description of Released Contaminant:** Diesel Fuel

**Volume Spilled:** 20.00 gallons      **Ag Related:** No

**EPA Extremely Hazardous Substance:** No      **Reported to NRC:** No

## Cause of Incident:

Guage reading was off on bulk tank. While filling the tank it overflowed out the top spilling approximately 15-20 gallons of fuel down the side of the tank and onto the ground.

## Risk Evaluation:

None

**# of Fatalities:** 0      **# of Injuries:** 0      **Affected Medium:** 03 - soil

## Potential Environmental Impacts:

None

## Action Taken or Planned:

Area is being excavated to remove the contaminated soil and placed into barrels.

**Wastes Disposal Location:** The material will be disposed of into an approved landfill.

## Agencies Involved:

## **Updates**

---

**Date:** 5/27/2015    **Status:** Reviewed - Follow-up Required

**Author:** Espe, Brady

**Updated Volume:**

**Notes:**

Overflow during filling the tank at facility site. Followup is required.

---

**Date:** 8/14/2015    **Status:** Inspection

**Author:** Espe, Brady

**Updated Volume:**

**Notes:**

I arrived at the site at 12:14 p.m. The weather was sunny, 91°F, with the wind from the northwest 10-15 mph. There was a small stain located on the west side of tank between the tank and building. The tank appears to be located in a low spot in the lot. Further followup needed. 46.83135, -100.95914

---

**Date:** 8/20/2015    **Status:** Correspondence

**Author:** Espe, Brady

**Updated Volume:**

**Notes:**

I talked to the company rep that reported the spill. He indicated that the area had been scraped up. He requested pictures of the area I saw and will have the manager look at the area. Pictures were sent.

---

**Date:** 12/22/2015    **Status:** Inspection

**Author:** Espe, Brady

**Updated Volume:**

**Notes:**

I arrived at the site 10:47 a.m. The weather was cloudy, 25°F, with wind from the southeast 10-15 mph. A second spill occurred on December 16, 2015; this spill occurred in the same area. Refer to Incident 3987 for further details on the cleanup.