

# General Environmental Incident Summary

**Incident:** 3761      **Date/Time Notice:** 5/26/2015      **DEM Incident No:**

**Responsible Party:** David Peyer

**Date Incident:** 3/14/2015      **Time Incident:** 0730      **Duration:**

**County:** McKenzie      **Twp:** 152      **Rng:** 101      **Sec:** 18      **Qtr:**

**Lat:** 47.98038      **Long:** -103.66330      **Method:** Interpolation from map

**Location Description:** ~12 miles south of Williston on Highway 85. ~0.15 miles right on 39th St. NW. On right hand side and rear of property.

**Submitted By:** Bridget Sedlack      **Affiliation:** Gibson Energy, LLC

**Address:** 3819 Towne Crossing Blvd

**City:** Mesquite      **State:** TX      **Zip:** 75150

## Received By:

### Contact Person:

870 36th Ave NW  
Cole Harbor, ND 58531

**Distance Nearest Occupied Building:**

**Release Contained:** Yes

**Type of Incident:** Tank Overflow

**Description of Released Contaminant:** Crude Oil

**Volume Spilled:**

**Ag Related:** No

**EPA Extremely Hazardous Substance:** Unknown

**Reported to NRC:** Unknown

### Cause of Incident:

Driver failed to gauge tanks before unloading

### Risk Evaluation:

None

**# of Fatalities:** 0      **# of Injuries:** 0      **Affected Medium:** 03 - soil

### Potential Environmental Impacts:

Impacted soils were excavated and removed.

### Action Taken or Planned:

Release occurred within secondary containment, however, approximately 12' of the berm leaked in the NW corner. It appeared that the liner was laid flat and the berm was built on top. A piece of conduit runs through the berm and oil was following that path. Hydrovac was used to clean inside containment area and impacted materials were removed. The failed berm section was excavated, relined and rebuilt. Clean pea gravel was spread inside containment. Impacted soils outside secondary containment were nominal, scrapped and disposed of properly with impacted media from inside the containment.

**Wastes Disposal Location:** Gibson Energy LLC, PRD

**Agencies Involved:**

**Updates**

---

**Date:** 5/26/2015    **Status:** Reviewed - Follow-up Required

**Author:** Stockdill, Scott

**Updated Volume:**

**Notes:**

According to the incident summary, this spill impacted areas not associated with an E & P location. Follow-up is necessary to ensure proper cleanup.

---

**Date:** 8/12/2015    **Status:** Inspection

**Author:** Espe, Brady

**Updated Volume:**

**Notes:**

I arrived at the site at 11:04 a.m. The weather was sunny, 101°F, with the wind from the northwest 0-5 mph. The facility is called Taylor. The area has been cleaned up, and I did not see any staining on top of gravel. The dike around the tanks looks newer. The area is surrounded by a gravel road that acts as another form of containment. No further followup needed at this time. 47.89397, -103.51225

---

**Date:** 8/20/2015    **Status:** Correspondence

**Author:** Espe, Brady

**Updated Volume:**

**Notes:**

Sent email requesting the sample results that show the spill was cleaned up, and any pictures, maps or other documentation regarding the cleanup.

---

**Date:** 8/24/2015    **Status:** Correspondence

**Author:** Espe, Brady

**Updated Volume:**

**Notes:**

Received the requested documentation on the spill cleanup.