

General Environmental Incident Summary

Incident: 3832 **Date/Time Notice:** 7/23/2015 1800 **DEM Incident No:**
Responsible Party: Johnson Bros.
Date Incident: 7/22/2015 **Time Incident:** 1830 **Duration:** 0.5 minutes
County: Williams **Twp:** 153 **Rng:** 101 **Sec:** 6 **Qtr:**
Lat: 48.10912 **Long:** -103.71770 **Method:** Interpolation from map
Location Description: Hwy 85 new Bridge Construction over the Missouri River, 2 miles south of Hwy 2 junction

Submitted By: Ryan Hood **Affiliation:** Johnson Bros.
Address: 4812 Southview Ave
City: Williston **State:** ND **Zip:** 58801

Received By:

Contact Person: Ryan Hood
4812 Southview Ave
Williston, ND 58801

Distance Nearest Occupied Building: 1 Miles **Release Contained:** Yes

Type of Incident: Vibro Hammer Hydraulic Oil

Description of Released Contaminant: EcoSure Biodegradable Hydraulic Oil

Volume Spilled: 1.00 gallons **Ag Related:** No

EPA Extremely Hazardous Substance: Unknown **Reported to NRC:** Unknown

Cause of Incident:

Vibro Hammer had a gasket seal fail. Hydraulic oil released from hammer into the cofferdam, and was contained in the cofferdam.

Risk Evaluation:

N/A - oil is biodegradable and the spill was contained and oil was removed from the water

of Fatalities: 0 **# of Injuries:** 0 **Affected Medium:** 02 - water

Potential Environmental Impacts:

No environmental impacts anticipated. The oil was removed from the effect water within the cofferdam.

Action Taken or Planned:

The contained oil was absorb using absorbing pads/boom, and removed from the water. The oil and clean absorbing pads/boom were taken to our oil recycling dumpster located off-site at the project office yard. Spill Reported to the EPA - NRC.

Wastes Disposal Location: The oil in our oil recycling dumpsters is removed by Safety Kleen on a regular basis.

Agencies Involved:

Updates

Date: 7/23/2015 **Status:** Reviewed - Assigned to NDDoH Division

Author: Crowdus, Kory

Updated Volume:

Notes:

Assigned to Peter Wax, Division of Water Quality.