

General Environmental Incident Summary

Incident: 3895 **Date/Time Notice:** 9/3/2015 1700 **DEM Incident No:**
Responsible Party: Nickelback Transport
Date Incident: 8/30/2015 **Time Incident:** 0400 **Duration:** 5 minutes
County: McKenzie **Twp:** 150 **Rng:** 99 **Sec:** 17 **Qtr:**
Lat: 47.81262 **Long:** -103.38320 **Method:** Interpolation from map
Location Description: From hwy 85, turn North on CR31, head north 2 miles. On West side of road

Submitted By: shawn holdaway **Affiliation:**
Address: 2209 124 ave
City: watford city **State:** ND **Zip:**

Received By:

Contact Person:

2209 124th ave
watford city, ND

Distance Nearest Occupied Building: 2 Miles **Release Contained:** Yes

Type of Incident: Vehicle Accident

Description of Released Contaminant: hydrolic oil with some production water mixed in

Volume Spilled: 2.00 gallons **Ag Related:** No

EPA Extremely Hazardous Substance: Unknown **Reported to NRC:** Unknown

Cause of Incident:

Truck hit soft shoulder and truck and trailer tipped into its side. Tanks integrity was intact but the scrubber vavle was damaged leaking oil onto side of road.

Risk Evaluation:

none

of Fatalities: **# of Injuries:** **Affected Medium:** 03 - soil

Potential Environmental Impacts:

none

Action Taken or Planned:

duck pond and bucket used to contain dripping.liquid

Wastes Disposal Location: liquid taken to alati disposal and soil removed and taken to shop
absorbtion containment

Agencies Involved:

Updates

Date: 9/8/2015 **Status:** Reviewed - Follow-up Required

Author: O'Gorman, Brian

Updated Volume:

Notes:

According to the report, a truck accident released 2 gallons of oil onto the side of the road. More followup needed.

Date: 9/9/2015 **Status:** Inspection

Author: Crowdus, Kory

Updated Volume:

Notes:

At location 9/9/2015, at 4:00 pm. Impact was to the ditch area on the west side of CR31. The area disturbed by the rollover was approximately 80x10ft. There was minor staining on the west side of gravel road. Some staining was also visible in ditch, but with tall grass it was difficult to determine extent of release. Field conductivity readings were taken in impacted area and showed a range of 7-17ms/cm. Soil samples were taken. More follow-up required.

Date: 6/7/2016 **Status:** Inspection

Author: Crowdus, Kory

Updated Volume:

Notes:

At location 6/7/2016, at 8:29am. Vegetation in ditch where release occurred is not growing. It does not appear that any cleanup work has been done at location. The area of dead vegetation is approximately 60x10ft. Surrounding vegetation in ditch area is green and growing without distress. Called contact and left message. More follow-up is required.

Date: 6/15/2016 **Status:** Correspondence

Author: Crowdus, Kory

Updated Volume:

Notes:

Spoke with contact via phone to discuss cleanup. It was indicated that they are awaiting quotes to come back for cleanup. NDDoH will be kept informed during the remediation process. Further follow-up is required.