

General Environmental Incident Summary

Incident: 3947 **Date/Time Notice:** 10/25/2015 1915 **DEM Incident No:**

Responsible Party: Boots Smith Oilfield Services

Date Incident: 10/24/2015 **Time Incident:** 1200 **Duration:**

County: McKenzie **Twp:** 153 **Rng:** 95 **Sec:** 4 **Qtr:**

Lat: 48.09884 **Long:** -102.89560 **Method:** Interpolation from map

Location Description: Pipeline Right-of-Way (ROW)

Submitted By: Alex Beach

Affiliation:

Address: 3015 16th Street SW, Suite

City: Minot

State: ND

Zip: 58701

Received By:

Contact Person: Dwight Brasseaux
2501 Airport Drive
Laurel, MS 39441

Distance Nearest Occupied Building: 1 Miles

Release Contained: No

Type of Incident: Water release

Description of Released Contaminant: water - The boring water was supplied from South of Hwy 23 Water Depot

Volume Spilled: 3.00 barrels

Ag Related: No

EPA Extremely Hazardous Substance: No

Reported to NRC: Unknown

Cause of Incident:

Approximately 3 bbls of water was released during the process of horizontal drill installation of a pipeline.

Risk Evaluation:

There were no injuries or evacuations that occurred as a result of this incident.

of Fatalities: 0

of Injuries: 0

Affected Medium: 03 - soil

Potential Environmental Impacts:

There are no expected environmental impacts at this time.

Action Taken or Planned:

Silt fence was placed at the point where the boring water exited the fracture to the surface and at multiple locations down the ravine in efforts to prevent the migration of the flow. A vac truck was dispatched to clean up the immediate area and also to vac up any future water release. The recovered fluids were put back into the system and re-used.

Wastes Disposal Location: The recovered fluids were put back into the system and re-used. If there are any wastes to be disposed of, they will be taken to an approved waste disposal facility.

Agencies Involved:

Updates

Date: 10/27/2015 **Status:** Reviewed - Follow-up Required

Author: Souder, Taylor

Updated Volume:

Notes:

According to incident report, release impacted area off location. Followup is required.

Date: 12/3/2015 **Status:** Inspection

Author: Espe, Brady

Updated Volume:

Notes:

I traveled to the different sites with the consultant working on the project. Incidents 3948, 3933, 3947, 3960, and 3943 all occurred in the same area. We arrived at the site 3:05 p.m. The weather was sunny, 41°F, with wind from the southwest 10-15 mph. These incidents occurred west of the Silurian Unit 6-1 battery in the draw. The site is accessed from the north along the new pipeline right of way. Access to the draw is not very easy. The fractures occurred high on the banks and flowed into the same area. The site has not been cleaned up; the mud and water are frozen. The plan is to meet with subcontractor on cleaning up the mud and water. Photos will be sent to verify cleanup. More followup needed. 48.09692, -102.89664

Date: 12/8/2015 **Status:** Correspondence

Author: Espe, Brady

Updated Volume:

Notes:

Received plan on how mud will be removed from the ravine.