

General Environmental Incident Summary

Incident: 3968 **Date/Time Notice:** 11/17/2015 1120 **DEM Incident No:**
Responsible Party: Halliburton Energy Services
Date Incident: 11/17/2015 **Time Incident:** 100 **Duration:** 25 minutes
County: Williams **Twp:** 156 **Rng:** 103 **Sec:** 36 **Qtr:**
Lat: 48.28525 **Long:** -103.88380 **Method:** Interpolation from map
Location Description: Halliburton Energy Services. 420 Halliburton Drive. Spill was outside the boundaries. Close to Hwy 1804
Submitted By: Ayo Olorunlogbon **Affiliation:** Halliburton
Address: 420 Halliburton Drive
City: Williston **State:** ND **Zip:** 58801

Received By:

Contact Person: Ayo Olorunlogbon
420 Halliburton Drive
Williston , ND 58801

Distance Nearest Occupied Building: 100 Feet **Release Contained:** No

Type of Incident: Tank Overflow

Description of Released Contaminant: Diesel

Volume Spilled: 40.00 gallons **Ag Related:** No

EPA Extremely Hazardous Substance: No **Reported to NRC:** Unknown

Cause of Incident:

Diesel transfer from equipment into drum. Employee left transfer and upon return, spill had occurred.

Risk Evaluation:

None

of Fatalities: 0 **# of Injuries:** 0 **Affected Medium:** 03 - soil

Potential Environmental Impacts:

Minimal impact on soil. Estimation of about 20 gallons outside property boundaries.

Action Taken or Planned:

Soil area will be excavated to ensure all contaminated soil is removed.

Wastes Disposal Location: Recovered waste will be disposed of at R360.

Agencies Involved:

Updates

Date: 11/19/2015 **Status:** Reviewed - Follow-up Required

Author: Crowdus, Kory

Updated Volume:

Notes:

Release impacted surrounding area. Follow-up is required.

Date: 11/20/2015 **Status:** Inspection

Author: Kangas, Kathleen

Updated Volume:

Notes:

Met company rep on site at 3:00 p.m. 36 degrees F, sunny, wind 40 mph NW. At the corner of Building 14 (corner of building near bridge), diesel went into the ditch. No standing water seen. Vac truck sucked up diesel. Within the next day or two, soil will be excavated and removed to permitted landfill.