

# General Environmental Incident Summary

**Incident:** 4118      **Date/Time Notice:** 6/6/2016      **DEM Incident No:**  
**Responsible Party:** Sterling Construction Management, LLC.  
**Date Incident:** 6/4/2016      **Time Incident:**      **Duration:** 1 minutes  
**County:** Dunn      **Twp:** 147      **Rng:** 96      **Sec:** 18      **Qtr:**  
**Lat:** 47.55449      **Long:** -102.96720      **Method:** Navigation quality GPS  
**Location Description:** Bear Creek Pipeline ROW STA. 815+85/Killdeer nearest town

**Submitted By:** Chase Edmiston      **Affiliation:**  
**Address:** 100 West Fifth St  
**City:** Tulsa      **State:** OK      **Zip:**

**Received By:**

**Contact Person:**

10020 HWY 200 East  
Dunn Center, ND

**Distance Nearest Occupied Building:**      **Release Contained:** Yes

**Type of Incident:** equipment failure

**Description of Released Contaminant:** hydraulic fluid

**Volume Spilled:**

**Ag Related:** No

**EPA Extremely Hazardous Substance:** Unknown

**Reported to NRC:** Unknown

**Cause of Incident:**

hydraulic hose connection failed on ditch machine

**Risk Evaluation:**

N/A

**# of Fatalities:**      **# of Injuries:**      **Affected Medium:** 03 - soil

**Potential Environmental Impacts:**

Localized soil contamination. No other sensitive resources affected.

**Action Taken or Planned:**

The spill was contained using a spill kit. The contaminated soil was shoveled into sand bags and transported to the Sterling yard for disposal. No evacuation was necessary and no sensitive resources were affected.

**Wastes Disposal Location:**

**Agencies Involved:**

## **Updates**

---

**Date:** 6/6/2016    **Status:** Reviewed - Follow-up Required

**Author:** Souder, Taylor

**Updated Volume:**                    0.50 gallons

**Notes:**

Contacted the responsible party and the release was not more than half a gallon of hydraulic fluid. Further follow-up needed.

---

**Date:** 8/4/2016    **Status:** No Further Action Requested

**Author:** Washek, Sandi

**Updated Volume:**                    0.50 gallons

**Notes:**

Arrived on site at 9:52 a.m. accompanied by company representative. Weather was overcast, and temperature was 69 degrees F. Equipment failure had hydraulic fluid leak on the ditch machine. The soil was cleaned up and removed. Inspection of the site showed no visible stained soil on pipeline row. The area is located in pasture land, and no water was impacted. No additional follow-up needed.