

General Environmental Incident Summary

Incident: 4150 **Date/Time Notice:** 6/28/2016 1643 **DEM Incident No:**

Responsible Party: Tesoro High Plains Pipeline

Date Incident: 6/28/2016 **Time Incident:** 1200 **Duration:**

County: McKenzie **Twp:** 150 **Rng:** 95 **Sec:** 18 **Qtr:** SE SE

Lat: 47.80461 **Long:** -102.87930 **Method:** Interpolation from map

Location Description: From the junction of Hwy 73 and Hwy 23 (Johnsons Corner), travel east on Hwy 73 for three miles, turn north on access road.

Submitted By: Mark Glaser

Affiliation:

Address: 2972 108S Ave SW

City: Dickinson

State: ND

Zip:

Received By:

Contact Person:

2972 108S Ave SW
Dickinson, ND, ND 58601

Distance Nearest Occupied Building: 1320 Feet

Release Contained: Yes

Type of Incident: Historical crude oil impacted soil, not active

Description of Released Contaminant: Crude Oil

Volume Spilled:

Ag Related: No

EPA Extremely Hazardous Substance: No

Reported to NRC: Unknown

Cause of Incident:

Cause and timing of release is unknown. The release is historic in nature.

Risk Evaluation:

There are no immediate risks with regard to explosive atmosphere, health risks, or to the public. Crude Oil is entrained in soils with no free liquid present.

of Fatalities: 0

of Injuries: 0

Affected Medium: 03 - soil

Potential Environmental Impacts:

Soil is impacted by crude oil with no impacts to surface water . Oil is entrained in soil with no free liquid observed. Impacts to ground water have not yet been evaluated.

Action Taken or Planned:

Excavated material will be stockpiled on site until proper disposal arrangements are made.

Wastes Disposal Location: To an approved special waste disposal.

Agencies Involved:

Updates

Date: 6/28/2016 **Status:** Reviewed - Follow-up Required

Author: Souder, Taylor

Updated Volume:

Notes:

Follow-up required.

Date: 6/30/2016 **Status:** Inspection

Author: Wax, Pete

Updated Volume:

Notes:

On site 0900. Overcast, 60 degrees, wind east at 10 mph. Nearest water 1/4 mile to the west. Met Mark Glaser (Tesoro environmentalist) on site and inspected site. Soil at location had variable levels of what appears to be crude or diesel. Tesoro plans to continue excavation and will dispose of soil at appropriate facilities and backfill with clean material. Verification samples from excavation hole (bottom and side wall) will be collected and provided to NDDoH (Bill Suess). Off site 10:00.

Date: 7/11/2016 **Status:** Inspection

Author: Schiermeister, Robin

Updated Volume:

Notes:

Arrived on 7-7-16 at 12:59. The excavation was in process. Further follow-up is needed.

Date: 8/31/2016 **Status:** Correspondence

Author: Schiermeister, Robin

Updated Volume:

Notes:

Received remediation plan which can be found in the reports folder. A plan is in place for six borings to fully delineate the soil in the northeast and southwest areas where contamination was found. Further follow-up needed.
