

Oil Field Environmental Incident Summary

Incident: 20121206190450 **Date/Time of Notice:** 12/06/2012 17:35

Responsible Party: WHITING OIL AND GAS CORPORATION

Well Operator: WHITING OIL AND GAS CORPORATION

Well Name: ARNEGARD 21-26H

Field Name: WILDCAT

Well File #: 19684

Date Incident: 12/5/2012 **Time Incident:** 13:07

Facility ID Number:

County: MCKENZIE

Twp: 150 **Rng:** 100 **Sec:** 26 **Qtr:** NE NW

Location Description: FROM FLARE PIT-WIND BLEW 3 1/2 Bbls MIST TO THE NE OF THE PIT-OFF LOCATION-INTO LANDOWNER FIELD.

Submitted By: Adam Rookey

Received By:

Contact Person: MITCH HAUGEBOG
1700 BROADWAY STE 2300
DENVER, CO 80290

General Land Use: Cultivated

Affected Medium: Topsoil

Distance Nearest Occupied Building: 2240 Feet

Distance Nearest Water Well: 2240 Feet

Type of Incident: Treater Popoff

Release Contained in Dike: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	0.25	barrels	0	barrels	0	
Brine	5.5	barrels	0	barrels	0	
Other	0	barrels	0	barrels		

Description of Other Released Contaminant:

Inspected: **Written Report Received:** 12/16/2013 **Clean Up Concluded:** 12/10/2012

Risk Evaluation:

TO BE DETERMINED-CLEAN UP CREW ON SITE

Areal Extent:

150 X 40

Potential Environmental Impacts:

TO BE DETERMINED

Action Taken or Planned:

FLUID FLOW WAS REROUTED TO DIFFERENT TREATER AND THE PROCESS QUIT FLOWING TO FLARE PIT. THERE WAS NO FREE STANDING FLUIDS TO RECOVER. A CREW WAS ASSIGNED, THEY LAID DOWN A PIT LINER ON LOCATION AND BUILT DIKES AROUND IT TO STORE CONTAMINATED SOILS. CREWS STARTED TO SHOVEL UP CONTAMINATED SOILS TILL DARK. THEY WILL RESUME CLEANUP IN THE MORNING.

Wastes Disposal Location: INDIAN HILL

Agencies Involved:

Updates

Date: 12/7/2012 **Status:** Reviewed - Follow-up Required

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release of some oil, and mostly brine blew off location as mist. Onsite follow-up with sample is required.

Date: 1/22/2013 **Status:** Inspection

Author: Clary, Shane

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Shane Clary and Adam Miller inspected and met with company personnel, Whiting's Environmental Coordinator, on location. The mist went off location to the northeast of the flare. Contaminated soil was excavated and taken to Indian Hills. The impacted soil was then replaced with clean soil. Whiting personnel supplied us with the analytical results from soil sampling that they completed after the spill.