

Oil Field Environmental Incident Summary

Incident: 20130103154251 **Date/Time of Notice:** 01/03/2013 15:38

Responsible Party: Rodney Conway

Well Operator: ENDURO OPERATING, LLC

Well Name: TENNECO 1-17

Field Name: MCKINNEY

Well File #: 10790

Date Incident: 1/1/2013 **Time Incident:** 08.00

Facility ID Number:

County: RENVILLE

Twp: 161

Rng: 86

Sec: 17

Qtr:

Location Description:

Submitted By: Rodney Conway

Received By:

Contact Person: Rodney Conway
777 MAIN STREET
SUITE 800
FORT WORTH, TX 76102

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building: 1 Miles

Distance Nearest Water Well: 1 Miles

Type of Incident: Pipeline Leak

Release Contained in Dike: Yes - Within Dike

Reported to NRC: Unknown

	Spilled	Units	Recovered	Units	Followup	Units
Oil	5	barrels	5	barrels		
Brine	0	barrels	0	barrels		
Other	0	barrels	0	barrels		

Description of Other Released Contaminant:

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

none

Areal Extent:

Potential Environmental Impacts:

none

Action Taken or Planned:

Sucked up and put in Oil tak. Replaced rubber in vic coupler

Wastes Disposal Location:

Agencies Involved:

Updates

Date: 1/4/2013 **Status:** Reviewed - Assigned to Other Agency

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Pipeline leak occurred, and was contained on location, within the dike system, according to the report.