

Oil Field Environmental Incident Summary

Incident: 20130115110210 **Date/Time of Notice:** 01/15/2013 10:57

Responsible Party: SM Energy Company

Well Operator: SM ENERGY COMPANY

Well Name: ECKERT 2-5HR

Field Name: INDIAN HILL

Well File #: 10089

Date Incident: 1/14/2013 **Time Incident:** 13:20

Facility ID Number:

County: MCKENZIE

Twp: 152

Rng: 101

Sec: 5

Qtr: NE SW

Location Description:

Submitted By: Luke Studer

Received By:

Contact Person: Luke Studer
PO BOX 7168
BILLINGS, MT 59103-7168

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building: 1 Miles

Distance Nearest Water Well: 1 Miles

Type of Incident: Truck Overflow

Release Contained in Dike: Yes - On Constructed Well Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	0	barrels	0	barrels		
Brine	3	barrels	3	barrels		
Other	0	barrels	0	barrels		

Description of Other Released Contaminant:

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

None

Areal Extent:

N/A

Potential Environmental Impacts:

None

Action Taken or Planned:

Driver sucked up spilled salt water. Black Hills Trucking will clean affected area and replace the scoria on/near spill area.

Wastes Disposal Location: Recovered saltwater hauled to an approved disposal. Contaminated soil to be hauled to an approved disposal.

Agencies Involved:

Updates

Date: 1/15/2013 **Status:** Reviewed - Assigned to Other Agency

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release remained on location, according to the report.