

Oil Field Environmental Incident Summary

Incident: 20131028100348 **Date/Time of Notice:** 10/28/2013 09:55

Responsible Party: rODNEY cONWAY

Well Operator: ENDURO OPERATING, LLC

Well Name: GOODMAN 15-16

Field Name: PORTAL

Well File #: 9372

Date Incident: 9/21/2013 **Time Incident:** 11.00

Facility ID Number:

County: BURKE

Twp: 163

Rng: 91

Sec: 16

Qtr:

Location Description:

Submitted By: Rodney Conway

Received By:

Contact Person: Rodney Conway
777 MAIN STREET
SUITE 800
FORT WORTH, TX 76102

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building: 3 Miles

Distance Nearest Water Well: 3 Miles

Type of Incident: Treater Leak

Release Contained in Dike: Yes - On Facility Site

Reported to NRC: Unknown

	Spilled	Units	Recovered	Units	Followup	Units
Oil	5	barrels	4	barrels		
Brine	0	barrels	0	barrels		
Other	0	barrels	0	barrels		

Description of Other Released Contaminant:

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

none

Areal Extent:

Potential Environmental Impacts:

none

Action Taken or Planned:

Used vac truck to suck up Oil. Soil removed and will be hauled to Tioga land fill.

Wastes Disposal Location: Prairie Disposal.

Agencies Involved:

Updates

Date: 10/28/2013 **Status:** Reviewed - Follow-up Required

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Spill remained on location, however due to the incident being reported over a month after it occurred follow-up should be done.

Date: 11/1/2013 **Status:** Reviewed - Assigned to Other Agency

Author: Espe, Brady

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

The spill occurred at the tank battery. The tank battery, separator, and flare are within a gravel dike. The dikes around the separator and flare have been worked on recently. The dike on the north side did not look the best. It appears the gravel within the dike system just east of the separator had been scrapped up. There is a small pile of gravel located on southeast side of the site. No contaminated soils piled at the site. Site is located along the north side of east/west county gravel road. No follow-up required at this time.