

# Oil Field Environmental Incident Summary

**Incident:** 20131202144537      **Date/Time of Notice:** 12/02/2013 14:20

**Responsible Party:** Hess Corporation

**Well Operator:** HESS CORPORATION

**Well Name:** BLMU CTB

**Field Name:** BEAVER LODGE

**Well File #:** 0

**Date Incident:** 12/2/2013      **Time Incident:** 10:12

**Facility ID Number:** 400045-06

**County:** WILLIAMS

**Twp:** 156

**Rng:** 95

**Sec:** 32

**Qtr:** SW SW

**Location Description:** Oil misted across road and into field to the west of location.

**Submitted By:** Courtney Wilhelm

**Received By:**

**Contact Person:** Courtney Wilhelm  
3015 16TH ST SW STE 20  
MINOT, ND 58701

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:** 0.5 Miles

**Distance Nearest Water Well:** 0.5 Miles

**Type of Incident:** Other

**Release Contained in Dike:** No

**Reported to NRC:** Unknown

|              | <b>Spilled</b> | <b>Units</b> | <b>Recovered</b> | <b>Units</b> | <b>Followup</b> | <b>Units</b> |
|--------------|----------------|--------------|------------------|--------------|-----------------|--------------|
| <b>Oil</b>   | 5              | barrels      | 0                | barrels      | 5               | barrels      |
| <b>Brine</b> | 0              | barrels      | 0                | barrels      |                 |              |
| <b>Other</b> | 0              | barrels      | 0                | barrels      |                 |              |

**Description of Other Released Contaminant:**

Oil

**Inspected:**

**Written Report Received:** 1/9/2014

**Clean Up Concluded:** 12/16/2013

**Risk Evaluation:**

None

**Areal Extent:**

**Potential Environmental Impacts:**

Visual impacts to ground surface.

**Action Taken or Planned:**

Treater was isolated to stop the leak, cleanup crew was dispatched to clean up spill, visual impacts will be cleaned up and disposed of.

**Wastes Disposal Location:** Clean Harbors

**Agencies Involved:**

**Updates**

---

**Date:** 12/2/2013    **Status:** Reviewed - Follow-up Required

**Author:** Stockdill, Scott

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

According to the report, the incident sprayed out across adjacent field. Followup is necessary.

---

**Date:** 12/4/2013    **Status:** Inspection

**Author:** Martin, Russell

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

16:05, on location. Site shows staining from mist blew W-SW. No noticeable staining on site scoria or vegetation directly adjacent to site on eastern side of road, but light staining on fence on western side of road. Awaiting phone call from Hess about cleanup actions taken.

---

**Date:** 12/5/2013    **Status:** Correspondence

**Author:** Martin, Russell

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Talked with Hess report contact; fine mist spread 260 feet to the west into field. Cleanup contractors cleaned mist impact to site grounds and roadway on 12/2-12/3. Due to weather, cleanup to field and fence delayed until Monday. Will need to follow up in a few weeks to confirm cleanup.

---

**Date:** 5/6/2014    **Status:** Inspection

**Author:** Martin, Russell

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

5/6/2014 at 16:10, on location. Fenceline appears cleaned. No visible staining to vegetation or in stubble field to southeast.