

Oil Field Environmental Incident Summary

Incident: 20131217170458 **Date/Time of Notice:** 12/17/2013 15:55

Responsible Party: Triangle USA Petroleum Corporation

Well Operator: TRIANGLE USA PETROLEUM CORPORATION

Well Name: STATE 152-102-36-25-2H

Field Name: ELK

Well File #: 25269

Date Incident: 12/15/2013 **Time Incident:**

Facility ID Number: 225036-01

County: MCKENZIE

Twp: 152 **Rng:** 102 **Sec:** 36 **Qtr:** SW SE

Location Description: A small amount of oil sprayed off the southwest of the location.

Submitted By: Amber Schaller

Received By:

Contact Person: Amber Schaller
1200 17TH ST., SUITE 2600
DENVER, CO 80202-5826

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building: 4920 feet

Distance Nearest Water Well: 4920 feet

Type of Incident: Other

Release Contained in Dike: No

Reported to NRC: Unknown

	Spilled	Units	Recovered	Units	Followup	Units
Oil	2	barrels	0	barrels	0	barrels
Brine	0	barrels	0	barrels		
Other	0	barrels	0	barrels		

Description of Other Released Contaminant:

Inspected:

Written Report Received: 3/7/2016

Clean Up Concluded: 12/16/2013

Risk Evaluation:

None

Areal Extent:

Approximately 30x40 area southwest of the well pad

Potential Environmental Impacts:

None

Action Taken or Planned:

Garner Environmental Services was contacted to haul the contaminated soil to an approved disposal facility.

Wastes Disposal Location:

Agencies Involved:

Updates

Date: 12/18/2013 **Status:** Reviewed - Follow-up Required

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to unspecified cause, sprayed off location. Followup is necessary.

Date: 12/27/2013 **Status:** Inspection

Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on location 12/27/13 at 11:00 CT. Weather conditions: partly cloudy, 34 F, 0-5 mph wind. Observed site and took photographs. Area south of well pad was covered by 6 to 8 inches of snow, and sparse vegetation was showing; however, the release direction was determined from fence posts having a concentration of oil on the east sides, which covered an area of approximately 250 feet from the west to east and approximately 50 feet from the well pad. Additional oil was very sparse on the vegetation south of the fence line, determined with the "tissue" test. Total impact could not be determined at this time due to snow depth off the well pad; however, impact did not appear very dense on the vegetation showing past the well pad fence line. Follow up in spring during snowmelt.

Date: 6/10/2015 **Status:** Inspection

Author: Washek, Sandi

Updated Oil Volume: 2.00 barrels

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on site at 1:48 p.m. Weather was overcast, temp 65 degrees F, wind east 10 mph. Walked the north side of the pad in an area of about 300 feet in length and 150 feet in width. Did not observe any sign of oil spray or vegetation stress from the fence line of the pad to the north side of the haul road. The area had good vegetation growth on the site. No additional followup required.