

# Oil Field Environmental Incident Summary

**Incident:** 20131223075729      **Date/Time of Notice:** 12/23/2013 07:34

**Responsible Party:** XTO ENERGY INC.

**Well Operator:** XTO ENERGY INC.

**Well Name:** SEEL 2-1

**Field Name:** BUFORD

**Well File #:** 12777

**Date Incident:** 12/22/2013      **Time Incident:** 1000

**Facility ID Number:**

**County:** WILLIAMS

**Twp:** 152      **Rng:** 104      **Sec:** 2      **Qtr:**

**Location Description:**

**Submitted By:** Scot Richardson

**Received By:**

**Contact Person:** Scot Richardson  
P.O Box 6506  
Williston, ND 58801

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:**

**Distance Nearest Water Well:**

**Type of Incident:** Treater Popoff

**Release Contained in Dike:** Yes - On Constructed Well Site

**Reported to NRC:** Unknown

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>
<b>Oil</b>	35	barrels	0	barrels
<b>Brine</b>	0	barrels	0	barrels
<b>Other</b>	0	barrels	0	barrels

**Followup**      **Units**

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:**

**Clean Up Concluded:**

**Risk Evaluation:**

none

**Areal Extent:**

**Potential Environmental Impacts:**

none

**Action Taken or Planned:**

Well was shut in and spill was contained in treater berm (unlined). Hot oil and vac truck will remove liquids. Roustabout crew will handle cleanup and remove any impacted soils to Indian Hills Disposal.

**Wastes Disposal Location:** Indian Hills Disposal.

**Agencies Involved:**

**Updates**

---

**Date:** 12/23/2013 **Status:** Reviewed - Assigned to Other Agency

**Author:** Stockdill, Scott

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

According to the incident summary, this incident, caused by a release through the treater popoff valve, remained on location within the dikes. NDIC retains oversight.