

Oil Field Environmental Incident Summary

Incident: 20140124181030 **Date/Time of Notice:** 01/24/2014 17:54

Responsible Party: Trade Star, LLC

Well Operator: XTO ENERGY INC.

Well Name: STAR 21X-14F

Field Name: GRINNELL

Well File #: 24858

Date Incident: 1/15/2014 **Time Incident:** 08:10

Facility ID Number:

County: WILLIAMS

Twp: 154

Rng: 97

Sec: 14

Qtr: NE NW

Location Description: 300 feet from Star 21X-14F location the north side of a private lease road and 1 mile off of 1804

Submitted By: Allen Harper

Received By:

Contact Person: Allen Harper
P.O Box 6501
Englewood, CO 80155

General Land Use: Pasture

Affected Medium: Topsoil

Distance Nearest Occupied Building: 2000 Feet

Distance Nearest Water Well: 1 Miles

Type of Incident: Vessel Leak

Release Contained in Dike: Yes - Within Dike

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	8	barrels	8	barrels		
Brine	0	barrels	0	barrels		
Other	0	barrels	0	barrels		

Description of Other Released Contaminant:

Crude Oil

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

contact with skin, flammable liquid, noursies fumes

Areal Extent:

Potential Environmental Impacts:

The environmental impact to surface soil was minimal the ground be frozen solid and also due to the vac truck sucking up the crude oil as it was exiting the tank through the small crack in the side.

Action Taken or Planned:

Clean Up: Once the truck and trailer were removed, WISE was able to change focus from containment and prevention of contamination and begin the clean up process. They sucked up all of the snow and oil that was left. It took WISE 10 minutes to suck it up. Then Trade Star had a backhoe scrape the ice and dirt into a pile and had WISE suck it up and haul it away to Indian Hills Landfill. WISE removed 40 BBLs of contaminated soil. Quality Carrier's vac truck also removed the oil it sucked up through the vent line of the wrecked trailer and put it into the Star21X-14F water tank per direction of XTO pumper Darrel. The QC driver estimated the volume at 15-22 BBLs. Trade Star brought in clean top soil to replace the contaminated soil that was removed.

Wastes Disposal Location: Indian Hills Environmental

Agencies Involved: State Inspector

Updates

Date: 1/25/2014 **Status:** Reviewed - Follow-up Required

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release was due to truck incident on lease road. Release was not contained and not reported in timely manner. Followup is necessary.

Date: 2/7/2014 **Status:** Inspection

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

2/7/2014 - 11:05 on location. Was met by a company representative who pointed out the location of the truck leak, 1000 ft to the west of the location on the lease road. Inspection of the area showed evidence of the cleanup. Impacted area was scraped, and no visual indication of residual oils or oil stains remain. No further inspections are necessary.