

Oil Field Environmental Incident Summary

Incident: 20140207133526 **Date/Time of Notice:** 02/07/2014 13:29

Responsible Party: EOG Resources, Inc.

Well Operator: EOG RESOURCES, INC.

Well Name: VANVILLE 15-1102H

Field Name: THOMPSON LAKE

Well File #: 20076

Date Incident: 2/7/2014 **Time Incident:** 10:30

Facility ID Number:

County: BURKE

Twp: 159

Rng: 91

Sec: 11

Qtr: SE SW

Location Description:

Submitted By: Luigi Heydt

Received By:

Contact Person: Luigi Heydt
600 17TH ST STE 1000N
DENVER, CO 80202

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: Yes - Within Dike

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	0	barrels	0	barrels		
Brine	3	barrels	0.5	barrels	3	barrels
Other	0	barrels	0	barrels		

Description of Other Released Contaminant:

Inspected:

Written Report Received: 8/29/2016

Clean Up Concluded: 3/10/2014

Risk Evaluation:

Areal Extent:

Potential Environmental Impacts:

Action Taken or Planned:

The free fluid was removed using a vac truck. The soil is going to be removed using shovels and a skid steer and disposed of.

Wastes Disposal Location: Clean Harbors.

Agencies Involved:

Updates

Date: 2/7/2014 **Status:** Reviewed - Assigned to Other Agency

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary, this spill remained on location. NDIC retains oversight.