

Oil Field Environmental Incident Summary

Incident: 20140209094637 **Date/Time of Notice:** 02/09/2014 09:35
Responsible Party: Chris Barnhill
Well Operator: BURLINGTON RESOURCES OIL & GAS COMPANY LP
Well Name: NORMAN 44-33MBH
Field Name: JOHNSON CORNER **Well File #:** 27084
Date Incident: 2/7/2014 **Time Incident:** 1630 **Facility ID Number:**
County: MCKENZIE **Twp:** 151 **Rng:** 96 **Sec:** 33 **Qtr:**
Location Description:

Submitted By: Allen Wheeler **Received By:**
Contact Person:
PO Box 737
Arnegard, ND 58835

General Land Use: Well/Facility Site **Affected Medium:** Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Other

Release Contained in Dike: Yes - Within Dike **Reported to NRC:** Unknown

	Spilled	Units	Recovered	Units	Followup	Units
Oil	0	barrels	0	barrels		
Brine	0	barrels	0	barrels		
Other	15	barrels	15	barrels	15	barrels

Description of Other Released Contaminant:

Fresh Water Surface Hole Mud

Inspected: **Written Report Received:** 8/5/2016 **Clean Up Concluded:** 2/10/2014

Risk Evaluation:

Areal Extent:

Potential Environmental Impacts:

Action Taken or Planned:

Contained within diked area. Cam Lock changed out. Vac truck utilized to clean up spill

Wastes Disposal Location: Returned to the system

Agencies Involved:

Updates

Date: 2/10/2014 **Status:** Reviewed - Assigned to Other Agency

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, during drilling of surface casing, remained on location, according to the report. NDIC retains oversight.