

# Oil Field Environmental Incident Summary

**Incident:** 20140221155257      **Date/Time of Notice:** 02/21/2014 15:24

**Responsible Party:** BH Flowtest LLC

**Well Operator:** CONTINENTAL RESOURCES, INC.

**Well Name:** RAYMO 5-31H

**Field Name:** DOLPHIN

**Well File #:** 24320

**Date Incident:** 2/21/2014      **Time Incident:** 07:30

**Facility ID Number:**

**County:** DIVIDE

**Twp:** 161      **Rng:** 95      **Sec:** 31      **Qtr:**

**Location Description:** 0.5 bbls oil misted off-location to the south, across the county road, and on both sides of the lease road, approx. 150 ft x 200 ft

**Submitted By:** Stacy Aguirre

**Received By:**

**Contact Person:** Stacy Aguirre  
PO BOX 268870  
OKLAHOMA CITY, OK 73126

**General Land Use:** Other - Described Above

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:**

**Distance Nearest Water Well:**

**Type of Incident:** Other

**Release Contained in Dike:** No

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>	5	barrels	0	barrels	5	barrels
<b>Brine</b>	1	barrels	0	barrels	1	barrels
<b>Other</b>	0	barrels	0	barrels		

**Description of Other Released Contaminant:**

**Inspected:**      **Written Report Received:** 10/14/2016      **Clean Up Concluded:** 2/22/2014

**Risk Evaluation:**

none

**Areal Extent:**

see above

**Potential Environmental Impacts:**

location material

**Action Taken or Planned:**

well shut in, material on location will be removed and replaced, and misted snow off-location will be removed

**Wastes Disposal Location:** TBD

**Agencies Involved:**

**Updates**

---

**Date:** 2/21/2014    **Status:** Reviewed - Follow-up Required

**Author:** Stockdill, Scott

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

According to the incident summary, this spill impacted areas off of location. Followup is necessary.

---

**Date:** 2/26/2014    **Status:** Inspection

**Author:** O'Gorman, Brian

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Arrived on location at 10:45 CT, 2/26/14. Weather conditions: 8F, sunny, wind NW 20-30 mph. Observed site and took photos. Spoke with the production foreman and the environmental contacts from Continental. According to the production foreman, a majority of the release was north of the county road and had been cleaned up, which was verified through observation. South of the road, they were in the process of scraping the snow for removal, which was also verified at the time of inspection. The environmental specialist for Continental explained to me that they had contacted the landowner to the south and they agreed with their cleanup plan. Observations of the area south of the road showed very little impacts. Impacted snow and soils were being hauled to Prairie Disposal.