

Oil Field Environmental Incident Summary

Incident: 20140321155218 **Date/Time of Notice:** 03/21/2014 15:52

Responsible Party: TRIANGLE USA PETROLEUM CORPORATION

Well Operator: TRIANGLE USA PETROLEUM CORPORATION

Well Name: MONSON 152-102-35-26-2H

Field Name: ELK

Well File #: 27379

Date Incident: 3/20/2014 **Time Incident:** 00:00

Facility ID Number:

County: MCKENZIE

Twp: 152 **Rng:** 102 **Sec:** 35 **Qtr:**

Location Description:

Submitted By: Amber Schaller

Received By:

Contact Person: Amber Schaller
1200 17TH ST., SUITE 2600
1200 17th Street, Suite 2600
DENVER, CO 80202-5826

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Other

Release Contained in Dike: Yes - On Constructed Well Site

Reported to NRC: Unknown

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine						
Other	80	Barrels	75	Barrels	75	barrels

Description of Other Released Contaminant:

Invert mud.

Inspected:

Written Report Received: 3/7/2016

Clean Up Concluded: 3/21/2014

Risk Evaluation:

none

Areal Extent:

75' x 75'

Potential Environmental Impacts:

none

Action Taken or Planned:

Invert mud and contaminated gravel and scoria was sucked up with a vac truck and placed in the solids bin.

Wastes Disposal Location:

Agencies Involved:

Updates

Date: 3/21/2014 **Status:** Reviewed - Follow-up Required

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary, this spill remained on location. NDIC retains oversight.

Date: 8/21/2014 **Status:** Inspection

Author: Wax, Pete

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

On site 13:15, off site 13:45; overcast, N wind at 10, 71 degrees. Nearest water is Camp Creek, approximately 400 yards to the NE. Large wellpad, multiple wells and tanks. Tank battery contained by metal dike and wellpad diked with earth on all four sides. Walked completely around battery and viewed entire pad. Found no evidence of spill on or off site.