

# Oil Field Environmental Incident Summary

**Incident:** 20140414124535      **Date/Time of Notice:** 04/14/2014 12:45

**Responsible Party:** PETRO-HUNT, L.L.C.

**Well Operator:** PETRO-HUNT, L.L.C.

**Well Name:** QUALE 3X

**Field Name:** KEENE

**Well File #:** 7561

**Date Incident:** 4/12/2014      **Time Incident:** 10:00

**Facility ID Number:**

**County:** MCKENZIE

**Twp:** 153      **Rng:** 95      **Sec:** 31      **Qtr:**

**Location Description:** NW/NW Section 3 T152N R96W This site is in a field directly to the south of the well site on the next section. Just on the west side of McKenzie Co Rd #55.

**Submitted By:** Doug Hanson

**Received By:**

**Contact Person:** DOUG HANSON  
PO BOX 935  
BISMARCK, ND 58502

**General Land Use:** Cultivated

**Affected Medium:** Topsoil

**Distance Nearest Occupied Building:** 1 Mile

**Distance Nearest Water Well:**

**Type of Incident:** Pipeline Leak

**Release Contained in Dike:** No

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>	10	Barrels	10	Barrels	10	barrels
<b>Brine</b>	10	Barrels	10	Barrels	10	barrels

**Other**

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:** 1/19/2016

**Clean Up Concluded:** 5/10/2014

**Risk Evaluation:**

None

**Areal Extent:**

It broke in a field belonging to Mr. Wisness.

**Potential Environmental Impacts:**

There will be soils that have been contaminated. They will have to be removed and replaced as per Mr. Wisness direction.

**Action Taken or Planned:**

The line will be pressure tested.

**Wastes Disposal Location:** Solids will be taken to PDI R360 disposal near Tioga.

**Agencies Involved:**

**Updates**

---

**Date:** 4/14/2014    **Status:** Reviewed - Follow-up Required

**Author:** Roberts, Kris

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Release is due to an off-location pipeline leak on private property. Followup is necessary.

---

**Date:** 4/21/2014    **Status:** Inspection

**Author:** Espe, Brady

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

The weather was 62 °F, with wind from the northwest at 10 to 15 miles per hour. The spill occurred on the west side of a newly constructed Conoco Phillips well pad located in the northeast corner of the section. The spill occurred on the west side of pad in the area that was disturbed during the construction of the pad. The area was cleaned up; no evidence on impacted soil. Not sure if it will be seeded to vegetation or cropped in the future. I did not see any issues; further followup needed in the summer to see if vegetation is growing in the area.

---

**Date:** 6/17/2014    **Status:** Inspection

**Author:** Espe, Brady

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

The weather was 69 °F, clear, with wind from the east 10 to 15 miles per hour. The break area has recently been seeded with crop that is coming up. Everything looks good; no further followup is needed at this time.

---

**Date:** 11/19/2014    **Status:** Correspondence

**Author:** Espe, Brady

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

General information.