

Oil Field Environmental Incident Summary

Incident: 20140513100556 **Date/Time of Notice:** 05/13/2014 10:05

Responsible Party: WHITING OIL AND GAS CORPORATION

Well Operator: WHITING OIL AND GAS CORPORATION

Well Name: EIDE 41-13HR CTB

Field Name: TIMBER CREEK

Well File #:

Date Incident: 5/12/2014 **Time Incident:** 18:00 **Facility ID Number:** 225731-01

County: MCKENZIE **Twp:** 150 **Rng:** 100 **Sec:** 13 **Qtr:** NE NE

Location Description:

Submitted By: Adam Rookey

Received By:

Contact Person: Mitch Haugeberg
1700 BROADWAY STE 2300
DENVER, CO 80290

General Land Use: Cultivated

Affected Medium: Topsoil

Distance Nearest Occupied Building: 0.4 Mile

Distance Nearest Water Well: 0.4 Mile

Type of Incident: Other

Release Contained in Dike: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	1	Barrels			1	barrels

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received: 1/11/2016

Clean Up Concluded: 5/19/2014

Risk Evaluation:

To be Determined

Areal Extent:

To be Determined

Potential Environmental Impacts:

To be Determined

Action Taken or Planned:

No sign of ongoing/active leak or seep. Crews called in to do collect impacted surface material by chovel and place in container to be hauled to disposal.

Wastes Disposal Location: At an approved & Appropriate disposal

Agencies Involved:

Updates

Date: 5/13/2014 **Status:** Reviewed - Follow-up Required

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to an unspecified cause, was not contained. Followup is necessary.

Date: 5/15/2014 **Status:** Correspondence

Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Received phone call from Mr. Adam Rookey, Whiting contact, at 16:00. Discussed remediation options for impacted area, and his plan was to get workers into the cultivated field with shovels to remove the impacted soil tomorrow. This would eliminate removing additional topsoil from the field. Mr. Rookey concluded that he would contact me when the removal was complete.

Date: 5/15/2014 **Status:** Inspection

Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on location at 11:16, 5/15/14. Observed the site and took photos. Observations of the impacted areas showed that the release had originated from the southwest portion of the well pad and moved to the east portion of the well pad that had eroded from precipitation. The release then moved toward the southeast approximately 1000 feet, across a cultivated field. Digging of the soil showed that the impact was mainly on the top portion of the soil, with no impacts noted below .5 to 1 inch. Phone message was left with Whiting contact.

Date: 8/27/2014 **Status:** Inspection

Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on location at 18:01 CT. Sunny, 82 degrees F, south wind 10-20 mph. Walked impacted areas and took photos. Well pad had been reclaimed, and a portion of the field (approximately 50 feet in width) nearest the well pad had been bulldozed and leveled with no indications of the past release on the barren soil. Wheat was growing in the field south of the barren soil with no indications of impacts to the existing stand. No followup required at this time.