

Oil Field Environmental Incident Summary

Incident: 20140613122744 **Date/Time of Notice:** 06/13/2014 12:27

Responsible Party: DENBURY ONSHORE, LLC

Well Operator: DENBURY ONSHORE, LLC

Well Name: CHSU 13C-29NH 26

Field Name: CEDAR HILLS

Well File #: 16121

Date Incident: 6/12/2014 **Time Incident:** 15:00

Facility ID Number:

County: BOWMAN

Twp: 132

Rng: 106

Sec: 29

Qtr:

Location Description: Approximately 300 ft east of the well location

Submitted By: Josh Cuppy

Received By:

Contact Person: Allen Mitchell
5320 LEGACY DR
PLANO, TX 75024-3127

General Land Use: Pasture

Affected Medium: Topsoil

Distance Nearest Occupied Building: 1 Mile

Distance Nearest Water Well: 1 Mile

Type of Incident: Pipeline Leak

Release Contained in Dike: Yes - On Pipeline ROW

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	0.3	Barrels	0.3	Barrels	0.3	barrels
Brine	1	Barrels	1	Barrels	1	barrels

Other

Description of Other Released Contaminant:

None

Inspected:

Written Report Received: 2/17/2016

Clean Up Concluded: 10/16/2014

Risk Evaluation:

NONE

Areal Extent:

Contained within ROW in small catch hole.

Potential Environmental Impacts:

NONE

Action Taken or Planned:

Release was contained in a catch hole. Line was shut in. Line will be repaired. Fluids will be recovered and soil disposed.

Wastes Disposal Location: Approved landfill.

Agencies Involved: BLM

Updates

Date: 6/16/2014 **Status:** Reviewed - Follow-up Required

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary, this spill occurred on a pipeline right-of-way. Followup is necessary.

Date: 6/18/2014 **Status:** Inspection

Author: Espe, Brady

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

The weather was 60 °F, cloudy, with wind from the northwest 10-15 miles per hour. I located a culvert in the 300-foot distance from the well to the southeast; it has a yellow top. I walked the area and did not see any evidence of discharge outside of culvert. No further follow-up needed at this time.