

Oil Field Environmental Incident Summary

Incident: 20140703230236 **Date/Time of Notice:** 07/03/2014 23:02

Responsible Party: Statoil Oil and Gas LP

Well Operator: STATOIL OIL & GAS LP

Well Name: Pherrin 4Way pig launcher

Field Name:

Well File #:

Date Incident: 7/3/2014 **Time Incident:** 14:15

Facility ID Number:

County: WILLIAMS

Twp: 156 **Rng:** 100 **Sec:** 34 **Qtr:**

Location Description: The Pherrin 4 Way riser/piglauncher is located on a Statoil ROW near the corner of County Road 8 and 132nd Ave.

Submitted By: Jeremy Mohl

Received By:

Contact Person: Jeremy Mohl
14649 Brigham Dr.
Williston, ND 58801

General Land Use: Pasture

Affected Medium: Topsoil

Distance Nearest Occupied Building: 3 Mile

Distance Nearest Water Well: 3 Mile

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	7	Barrels	7	Barrels		

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received: 9/1/2016

Clean Up Concluded: 9/16/2014

Risk Evaluation:

Live stock still in the area. Crew installed a barb wire fence around the contaminated area and the riser system to keep livestock out

Areal Extent:

80 Ft wide at the source terminating approximately 190 ft. away from the source.

Potential Environmental Impacts:

Only the very top layer of soil has been impacted.

Action Taken or Planned:

Install plug on two inch drain line and also install cattle guard around the riser system.

Wastes Disposal Location: Prairie Disposal

Agencies Involved:

Updates

Date: 7/6/2014 **Status:** Reviewed - Follow-up Required

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release from an off-location pipeline leak into pasture land. Impact area has been fenced off until cleanup is complete. Followup is necessary.

Date: 7/11/2014 **Status:** Inspection

Author: Martin, Russell

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

7/11/2014 at 9:35, on location. Met with cleanup company personnel on site. According to personnel, cleanup is complete and topsoil is being replaced now. By noon, depending on truck reliability, fertilizer and reseedling of the ground should commence. During the inspection, some staining was observed on isolated clumps of vegetation and dirt clods from the excavation. Phone call into report contact as to plans on addressing this issue.

Date: 7/14/2014 **Status:** Correspondence

Author: Martin, Russell

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Phone call with report contact. Isolated clumps will be picked up and removed according to contact.

Date: 9/16/2014 **Status:** Inspection

Author: Martin, Russell

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

9/16/2014 at 10:49, on location. Work on pipeline right of way has caused some new work to occur at the location of the incident. No visible staining to vegetation or to area under pig launcher.