

# Oil Field Environmental Incident Summary

**Incident:** 20140713115812      **Date/Time of Notice:** 07/13/2014 11:58

**Responsible Party:** Oasis Petroleum

**Well Operator:** OASIS PETROLEUM NORTH AMERICA LLC

**Well Name:** KRISTIE 5300 13-13B

**Field Name:** WILLOW CREEK

**Well File #:** 24706

**Date Incident:** 7/13/2014      **Time Incident:** 07:00

**Facility ID Number:**

**County:** WILLIAMS

**Twp:** 153      **Rng:** 100      **Sec:** 13      **Qtr:** NW NE

**Location Description:**

**Submitted By:** Todd Hanson

**Received By:**

**Contact Person:** Todd Hanson  
1001 FANNIN STE 1500  
HOUSTON, TX 77002

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:** 1 Mile

**Distance Nearest Water Well:** 1 Mile

**Type of Incident:** Stuffing Box Leak

**Release Contained in Dike:** Yes - On Constructed Well Site

**Reported to NRC:** Unknown

|              | <b>Spilled</b> | <b>Units</b> | <b>Recovered</b> | <b>Units</b> | <b>Followup</b> | <b>Units</b> |
|--------------|----------------|--------------|------------------|--------------|-----------------|--------------|
| <b>Oil</b>   | 8              | Barrels      | 8                | Barrels      |                 |              |
| <b>Brine</b> | 2              | Barrels      | 2                | Barrels      |                 |              |

**Other**

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:**

**Clean Up Concluded:**

**Risk Evaluation:**

none

**Areal Extent:**

**Potential Environmental Impacts:**

minimal

**Action Taken or Planned:**

make sure pumpers know to turn units off before shutting in well.

**Wastes Disposal Location:** IDH

**Agencies Involved:**

**Updates**

---

**Date:** 7/14/2014    **Status:** Reviewed - Assigned to Other Agency

**Author:** Roberts, Kris

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Release, due to a stuffing box leak, remained on location according to the report. NDIC retains oversight.