

Oil Field Environmental Incident Summary

Incident: 20140718152749 **Date/Time of Notice:** 07/18/2014 15:27

Responsible Party: MARATHON OIL COMPANY

Well Operator: MARATHON OIL COMPANY

Well Name: DAVID BECK - USA 34-7H

Field Name: BAILEY

Well File #: 17493

Date Incident: 7/18/2014 **Time Incident:** 12:50

Facility ID Number:

County: DUNN

Twp: 146

Rng: 94

Sec: 7

Qtr:

Location Description:

Submitted By: Ashley Schaper

Received By:

Contact Person: Ashley Schaper
3172 HWY 22 N
3172 Hwy 22 N
DICKINSON, ND 58601

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Fire

Release Contained in Dike: No

Reported to NRC: No

Spilled Units

Recovered Units

Followup Units

Oil

Brine

Other

Description of Other Released Contaminant:

Oil out of the flare stack

Inspected:

Written Report Received: 10/9/2015

Clean Up Concluded: 7/25/2015

Risk Evaluation:

No immediate risks. Fire was extinguished quickly

Areal Extent:

3x20 area was not contained. Total area burned was 5x20

Potential Environmental Impacts:

Minimal potential environmental impacts.

Action Taken or Planned:

Clean up will be provided of the burned area.

Wastes Disposal Location: approved landfill.

Agencies Involved:

Updates

Date: 7/18/2014 **Status:** Reviewed - Follow-up Required

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Fire on location, plus reported off-location release. Followup is necessary.

Date: 7/21/2014 **Status:** Inspection

Author: Espe, Brady

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

The weather was 68°F, cloudy, with wind from the northeast 10-15 mph. The vegetation on the southeast corner of well pad and on the south side of pasture was impacted by the fire. No cleanup has occurred to this point. More followup is needed to check on cleanup.

Date: 8/14/2014 **Status:** Inspection

Author: Espe, Brady

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

The weather was 86 °F, with wind from the southeast at 20+ mph. None of the area has been mowed. The top of the grass in the area is starting to dry, including the grass on the southeast corner of pad. Near the flare, there are green shoots at the base of the grass that have a darker color. More follow-up needed to check on vegetation.

Date: 11/19/2014 **Status:** Correspondence

Author: Espe, Brady

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Plan of action regarding the burned-off area off of pad near flare. They are monitoring the area as it is more prone to erosion. They do not think the fire damaged the roots of the vegetation. If the vegetation has difficulty sprouting, they will seed the area with native seed mix.

Date: 6/1/2015 **Status:** Inspection

Author: Espe, Brady

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

I arrived at the site at 15:50 p.m. The weather is clear, 86°F, with the wind from the south 10-15 mph. The vegetation looks good; there is no evidence of the fire and spray. Compliance samples were taken. No further followup needed at this time.

Date: 1/27/2016 **Status:** Correspondence

Author: Espe, Brady

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Sent letter with samples and also requested more samples be taken at the site.

Date: 3/18/2016 **Status:** Correspondence

Author: Espe, Brady

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Talked to company contact, and they will continue to monitor the area.