

# Oil Field Environmental Incident Summary

**Incident:** 20140725160456      **Date/Time of Notice:** 07/25/2014 16:04

**Responsible Party:** Landtech Enterprises, LLC

**Well Operator:** LANDTECH ENTERPRISES, LLC

**Well Name:** Paluck #1 SWD

**Field Name:** ST. DEMETRIUS

**Well File #:** 13461

**Date Incident:** 7/19/2014      **Time Incident:** 13:20

**Facility ID Number:**

**County:** BILLINGS

**Twp:** 142

**Rng:** 99

**Sec:** 24

**Qtr:** NW SW

**Location Description:**

**Submitted By:** Mike Shannon

**Received By:**

**Contact Person:** Kirk R Johnson  
P.O. Box 1560  
Sidney, MT 59270

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:** 0.5 Mile

**Distance Nearest Water Well:** 0.5 Mile

**Type of Incident:** Tank Overflow

**Release Contained in Dike:** Yes - On Facility Site

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>						
<b>Brine</b>	6	Barrels	5	Barrels		
<b>Other</b>						

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:**

**Clean Up Concluded:**

**Risk Evaluation:**

None

**Areal Extent:**

**Potential Environmental Impacts:**

None

**Action Taken or Planned:**

Pumper shoveled dirt for dike to stop spill which covered a 2 foot by 20 foot area. The fluid was sucked up by a vac truck. He used the Bobcat to remove the dirt & put it in the roll-off. He spread new material on the ground and installed a new float

**Wastes Disposal Location:** Salt water from the spill will be run through the centrifuge and the solids will go to the Nuverra Landfarm.

**Agencies Involved:** Jessie Trotter, NDIC Inspector was notified 7/19/14

**Updates**

---

**Date:** 7/27/2014    **Status:** Reviewed - Assigned to Other Agency

**Author:** Roberts, Kris

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Release, due to a tank overflow, remained on location, within the diking, according to the report. NDIC retains oversight.