

Oil Field Environmental Incident Summary

Incident: 20140728114259 **Date/Time of Notice:** 07/28/2014 11:42

Responsible Party: SAMSON RESOURCES COMPANY

Well Operator: SAMSON RESOURCES COMPANY

Well Name: STINGRAY 18-19-162-98H

Field Name: AMBROSE

Well File #: 20801

Date Incident: 7/28/2014 **Time Incident:** 10:00

Facility ID Number:

County: DIVIDE

Twp: 162 **Rng:** 98 **Sec:** 18 **Qtr:**

Location Description:

Submitted By: Cooper Hearne

Received By:

Contact Person: Brad Rogers
2 W 2ND ST SAMSON PLAZA
TULSA, OK 74103-3101

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Other

Release Contained in Dike: Yes - On Constructed Well Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	1.5	Barrels	1.5	Barrels		

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

No Immediate environmental impact.

Areal Extent:

Potential Environmental Impacts:

No potential environmental impact to surface water groundwater or soils.

Action Taken or Planned:

Spilled liquid was cleaned up by a vac truck and residue was cleaned up with absorbant rags.

Wastes Disposal Location: Waste will be disposed of at an approved E&P disposal facility.

Agencies Involved:

Updates

Date: 7/29/2014 **Status:** Reviewed - Assigned to Other Agency **Author:** Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to an unspecified cause, remained on location, within the diking, according to the report. NDIC retains oversight.