

# Oil Field Environmental Incident Summary

**Incident:** 20140730185039      **Date/Time of Notice:** 07/30/2014 18:50

**Responsible Party:** MBI Energy Services

**Well Operator:** MOUNTAIN DIVIDE, LLC

**Well Name:** OLSON 35-26-1H

**Field Name:** WILDCAT

**Well File #:** 24544

**Date Incident:** 7/30/2014      **Time Incident:** 04:00

**Facility ID Number:**

**County:** DIVIDE

**Twp:** 163      **Rng:** 101      **Sec:** 35      **Qtr:**

**Location Description:**

**Submitted By:** Nathan Ehlis

**Received By:**

**Contact Person:** Nathan Ehlis  
12980 35th st sw  
Belfield, ND 58622

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:**

**Distance Nearest Water Well:**

**Type of Incident:** Tank Overflow

**Release Contained in Dike:** Yes - Within Dike

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>	1	Barrels	1	Barrels		

**Brine**

**Other**

**Description of Other Released Contaminant:**

No other released substances

**Inspected:**

**Written Report Received:**

**Clean Up Concluded:**

**Risk Evaluation:**

there is no risk to any thing outside of the berm, cleanup is in progress

**Areal Extent:**

The spill was contained within the berm of the oil well

**Potential Environmental Impacts:**

The only impact to the soil withing the berm.

**Action Taken or Planned:**

The spill was contained within the berm, Cleanup will be started today. The spill will be sucked up, gravel inside of the berm will be sprayed down, and any contaminated soil will be removed from the berm. Retraining of the employee will be done.

**Wastes Disposal Location:** All recovered oil, and wash water will be sent down hole at one of our disposals. all contaminated soil and gravel will be taken to Indian Hills for disposal

**Agencies Involved:**

**Updates**

---

**Date:** 7/31/2014    **Status:** Reviewed - Assigned to Other Agency

**Author:** Roberts, Kris

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Release, due to a tank overflow, remained on location, within the diking, according to the report. NDIC retains oversight.