

Oil Field Environmental Incident Summary

Incident: 20140802161528 **Date/Time of Notice:** 08/02/2014 16:15

Responsible Party: Emerald Oil, Inc

Well Operator: EMERALD OIL, INC

Well Name: RON BURGUNDY 3-23-14H

Field Name: TEMPLE

Well File #: 27334

Date Incident: 8/2/2014 **Time Incident:** 00:00

Facility ID Number:

County: WILLIAMS

Twp: 158

Rng: 96

Sec: 23

Qtr: SW SW

Location Description: Spill located on the Ron Burgundy 3-23-14H well site (Site).

Submitted By: Lynne Thomsen

Received By:

Contact Person: John Slagell
1600 Broadway, Suite 1360
Denver, CO 80202

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Tank Overflow

Release Contained in Dike: Yes - On Constructed Well Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	59	Barrels	58	Barrels		
Brine	1	Barrels	1	Barrels		

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

Low risk with containment provided at Site.

Areal Extent:

Potential Environmental Impacts:

The spill was contained on-site and did not impact surface water . The Site is lined with clay and fluids were quickly removed so impacts to groundwater is not expected. Some soils, all located on the Site, are in the process of being removed.

Action Taken or Planned:

All fluids from the Site have been removed. Contaminated soil at the Site is in the process of being removed. No further action is expected due to quick cleanup activities and the spill being contained on-site.

Wastes Disposal Location: Recovered oil was returned to the on-site tanks. Recovered brine was disposed of at the Justin SWD 1 disposal well, operated by Bosque Disposal Systems, LLC. Contaminated soils are expected to be disposed of at PDI, 10210 52nd St NW, Tioga, ND 58852.

Agencies Involved:

Updates

Date: 8/3/2014 **Status:** Reviewed - Assigned to Other Agency

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a tank leak, remained on location within the diking according to the report. NDIC retains oversight.