

Oil Field Environmental Incident Summary

Incident: 20140807215451 **Date/Time of Notice:** 08/07/2014 21:54
Responsible Party: ZAVANNA, LLC
Well Operator: ZAVANNA, LLC
Well Name: EVERETT 1-15H
Field Name: STOCKYARD CREEK **Well File #:** 20510
Date Incident: 8/7/2014 **Time Incident:** 20:00 **Facility ID Number:**
County: WILLIAMS **Twp:** 154 **Rng:** 99 **Sec:** 15 **Qtr:**

Location Description:

Submitted By: Drew Tooley **Received By:**
Contact Person: Drew Tooley
1200 17TH STREET STE 1100
DENVER, CO 80202

General Land Use: Well/Facility Site **Affected Medium:** Well/Facility Soil

Distance Nearest Occupied Building: 0.4 Mile
Distance Nearest Water Well: 0.4 Mile

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: Yes - On Constructed Well Site **Reported to NRC:** Unknown

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	3	Barrels	2.8	Barrels		
Other					2.9	barrels

Description of Other Released Contaminant:

[Redacted area]

Inspected: **Written Report Received:** 9/8/2014 **Clean Up Concluded:** 8/8/2014

Risk Evaluation:
None

Areal Extent:

Potential Environmental Impacts:

Well site Facility

Action Taken or Planned:

The crew set up a dike around the spill and had a cleanup crew out immediately to recover spilled water. Stabbed TIW valve in the tubing and closed TIW valve to control spill. Future prevention will be to install TIW valve before pumping.

Wastes Disposal Location: Water disposed at Grasser SWD and solids disposed at Indian Hills Disposal

Agencies Involved:

Updates

Date: 8/11/2014 **Status:** Reviewed - Assigned to Other Agency

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to an on-location valve/piping leak, remained on location according to the report. NDIC retains oversight.