

Oil Field Environmental Incident Summary

Incident: 20140915083304 **Date/Time of Notice:** 09/15/2014 08:33

Responsible Party: Trican Energy Services

Well Operator: OXY USA INC.

Well Name: STATE DVORAK A 2-16-21H-142-96

Field Name: MANNING

Well File #: 27958

Date Incident: 9/14/2014 **Time Incident:** 16:00

Facility ID Number:

County: DUNN

Twp: 142

Rng: 96

Sec: 9

Qtr:

Location Description:

Submitted By: Dustin Tescher

Received By:

Contact Person: Dustin Tescher
5 GREENWAY PLAZA STE 110
HOUSTON, TX 77046-0506

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building: 3.3 Mile

Distance Nearest Water Well: 3.3 Mile

Type of Incident: Pump Leak

Release Contained in Dike: Yes - On Constructed Well Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	2	Barrels	2	Barrels	2	barrels
Other						

Description of Other Released Contaminant:

Inspected:

Written Report Received: 9/15/2014

Clean Up Concluded: 9/14/2014

Risk Evaluation:

NA

Areal Extent:

Potential Environmental Impacts:

NA

Action Taken or Planned:

NA

Wastes Disposal Location: All fluid was recovered and put back into the storage tanks for use on the frac.

Agencies Involved:

Updates

Date: 9/15/2014 **Status:** Reviewed - Assigned to Other Agency

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a pump leak, remained on location during fracking activities according to the report. NDIC retains oversight.