

Oil Field Environmental Incident Summary

Incident: 20140919203616 **Date/Time of Notice:** 09/19/2014 20:36

Responsible Party: CONTINENTAL RESOURCES, INC.

Well Operator: CONTINENTAL RESOURCES, INC.

Well Name: MADISON 1-28H

Field Name: DOLLAR JOE

Well File #: 20791

Date Incident: 9/19/2014 **Time Incident:** 08:00

Facility ID Number:

County: WILLIAMS

Twp: 155

Rng: 97

Sec: 28

Qtr:

Location Description:

Submitted By: Todd Senescall

Received By:

Contact Person: Jared Enger
PO BOX 268870
OKLAHOMA CITY, OK 73126

General Land Use: Pasture

Affected Medium: Topsoil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Treater Leak

Release Contained in Dike: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	2	Barrels	1.5	Barrels	1.95	barrels

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received: 6/5/2015

Clean Up Concluded: 9/20/2014

Risk Evaluation:

fire

Areal Extent:

Approximately 1/3 acre of pasture and several trees were affected.

Potential Environmental Impacts:

soil and vegetation

Action Taken or Planned:

treater isolated, standing liquid sucked up. Contaminated soil recovery in progress. Landowner and NDIC inspector notified. Area will be evaluated tomorrow to determine if S-200 application in trees is warranted. While no production water release is suspected, soil sampling will be done to confirm.

Wastes Disposal Location: Liquid - SWD
Soils - TDB

Agencies Involved:

Updates

Date: 9/22/2014 **Status:** Reviewed - Follow-up Required

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a treater leak, sprayed off location. Followup is necessary.

Date: 9/25/2014 **Status:** Inspection

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

9/25/14 - 18:30 on location. Photos with GPS embedded. Spray off location into same trees impacted with last spray release in July. Wind direction was more from the west so the spray went much farther down the very steep draw in the pasture. Cattle are in this pasture with access to this area as of this date and time. It appears that there has been some vegetation cutting (or heavy grazing) from the last spray, which covered the knob to the south and west of the trees and the westernmost trees. This time the trees took the brunt of the spray, as well as the area down to the east into the ravine. NDDoH will pass photos from both incidents along to Dr. Keller for information and discuss these two incidents directly with Continental Resources. Another inspection in spring of 2015 is needed to determine whether grove of trees have recovered, and if erosion on the south side if the location is under control.

Date: 6/10/2016 **Status:** Correspondence

Author: Suess, Bill

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Bill Suess sent a No Further Action letter dated June 10, 2016.

Date: 6/10/2016 **Status:** Inspection

Author: Suess, Bill

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Visited the site on 6/6/2016. Vegetation appears healthy with no signs of impact. No further action is warranted.