

Oil Field Environmental Incident Summary

Incident: 20140926172153 **Date/Time of Notice:** 09/26/2014 17:21

Responsible Party: OXY USA INC.

Well Operator: OXY USA INC.

Well Name: EMIL VEVERKA 2-17-20H-143-95

Field Name: MURPHY CREEK

Well File #: 21264

Date Incident: 9/26/2014 **Time Incident:** 09:00

Facility ID Number:

County: DUNN

Twp: 143

Rng: 95

Sec: 17

Qtr:

Location Description:

Submitted By: Robyn Espinoza

Received By:

Contact Person: Robyn Espinoza
5 GREENWAY PLAZA STE 110
HOUSTON, TX 77046-0506

General Land Use: Well/Facility Site

Affected Medium: Topsoil

Distance Nearest Occupied Building: 0.2 Mile

Distance Nearest Water Well: 0.2 Mile

Type of Incident: Treater Leak

Release Contained in Dike: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	6	Barrels	4	Barrels	4	barrels

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received: 1/21/2016

Clean Up Concluded: 11/8/2014

Risk Evaluation:

Contaminated surface material

Areal Extent:

Adjacent land directly west of the location.

Potential Environmental Impacts:

Contaminated surface material

Action Taken or Planned:

The well was shut in to prevent any further release, Rud was dispatched and recovered all standing liquids, SM Fencinc has cut and bagged all affected vegetation and any other contaminated material will be removed and disposed of.

Wastes Disposal Location: Chimney Butte

Agencies Involved:

Updates

Date: 9/29/2014 **Status:** Inspection

Author: Martin, Russell

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

9/29/2014 at 16:30, on location. Oxy and contractor personnel onsite. Release sprayed from western-most treater, blew ~due west into vegetation on site and pasture off site. Facility fence has visible staining. Pasture fence ~60 ft further to the west is rusted and may have light impact. Some vegetation cut and bagged, and bags are visible on location. However, uncut vegetation in small pasture between fences shows staining. Called report contact; vegetation in pasture will be cut as well. Landowner has been notified.

Date: 9/29/2014 **Status:** Reviewed - Follow-up Required

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release from a treater leak sprayed off location. Followup is necessary.

Date: 11/12/2014 **Status:** Inspection

Author: Martin, Russell

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

11/12/2014 at 14:28, on location. Most of vegetation in impact area cut and removed. While there is no visible impact to vegetation outside of cut area, there is some light staining when wiped. Remaining staining is light enough it should naturally attenuate.