

Oil Field Environmental Incident Summary

Incident: 20141030124349 **Date/Time of Notice:** 10/30/2014 12:43

Responsible Party: HESS BAKKEN INVESTMENTS II, LLC

Well Operator: HESS BAKKEN INVESTMENTS II, LLC

Well Name: GO-PERDUE- 157-97-0112H-4

Field Name: RAY

Well File #: 28994

Date Incident: 10/29/2014 **Time Incident:** 16:45

Facility ID Number:

County: WILLIAMS

Twp: 157 **Rng:** 97 **Sec:** 1 **Qtr:**

Location Description:

Submitted By: Jason Henry

Received By:

Contact Person: Jason Henry
3015 16t Street SW, Suite 20
Minot, ND 58701

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building: 0.5 Mile

Distance Nearest Water Well: 0.5 Mile

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: Yes - Within Dike

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine						
Other	8.2	Barrels	8.2	Barrels	8.2	barrels

Description of Other Released Contaminant:

Oil Based Mud (OBM)

Inspected:

Written Report Received: 3/4/2015

Clean Up Concluded: 10/30/2014

Risk Evaluation:

The released OBM was contained on location, and the released OBM was recovered and returned to active system using the rig vac and pressure washers.

Areal Extent:

N/A - contained on the location

Potential Environmental Impacts:

There were no potential receptors observed in the immediate vicinity of the release location. The released OBM was contained on location, and the released OBM was recovered and returned to active system using the rig vac and pressure washers.

Action Taken or Planned:

There were no potential receptors observed in the immediate vicinity of the release location. The released OBM was contained on location, and the released OBM was recovered and returned to active system using the rig vac and pressure washers.

Wastes Disposal Location: N/A - The released OBM was recovered and returned to active system using the rig vac and pressure washers.

Agencies Involved:

Updates

Date: 10/31/2014 **Status:** Reviewed - Assigned to Other Agency

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to an on-location valve/piping leak during drilling activities, remained on location within the diking according to the report. NDIC retains oversight.