

Oil Field Environmental Incident Summary

Incident: 20141104154004 **Date/Time of Notice:** 11/04/2014 15:40

Responsible Party: HESS BAKKEN INVESTMENTS II, LLC

Well Operator: HESS BAKKEN INVESTMENTS II, LLC

Well Name: TIOGA-MADISON UNIT N-132D

Field Name: TIOGA

Well File #: 90052

Date Incident: 11/3/2014 **Time Incident:** 10:00

Facility ID Number:

County: MOUNTRAIL

Twp: 158

Rng: 94

Sec: 31

Qtr: NE NE

Location Description: Hess TMU G135 to TMU N132D produced water pipeline ROW - 30-158-94

Submitted By: Jason Henry

Received By:

Contact Person: Jason Henry
1501 MCKINNEY
HOUSTON, TX 77010

General Land Use: Pasture

Affected Medium: Topsoil

Distance Nearest Occupied Building: 0.2 Mile

Distance Nearest Water Well: 0.2 Mile

Type of Incident: Pipeline Leak

Release Contained in Dike: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	0.5	Barrels				
Brine	0.5	Barrels				

Other

Description of Other Released Contaminant:

Approximately 0.5 bbls of produced water and approximately 0.5 bbls of crude oil were released from Hess' TMU G135 -TMU N132D produced water pipeline

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

The release has been secured and the pipeline is de-pressured awaiting repairs to be made.

Areal Extent:

Approximately 750 square feet of visibly impacted surface soil

Potential Environmental Impacts:

The release has been secured and the pipeline is de-pressured awaiting repairs to be made. There were no potential receptors observed in the immediate vicinity of the release location.

Action Taken or Planned:

The release has been secured and the pipeline is de-pressured awaiting repairs to be made. The impacted soil will be excavated, stockpiled, and transported off-site for disposal at a properly permitted disposal facility.

Wastes Disposal Location: Prairie Disposal LLC south of Tioga, ND

Agencies Involved:

Updates

Date: 11/4/2014 **Status:** Reviewed - Follow-up Required

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary, this spill occurred on a pipeline ROW. More followup is necessary.

Date: 11/20/2014 **Status:** Awaiting Documentation

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

11/20/14 - 16:10 on location. Location is 158-94-30 SE of NW. Entry from north on the east side of the farmstead in NW quarter. Shallow salt brine pipeline of fiberglass failed. Identified by large dead area in otherwise heavily vegetated low area. There are additional areas that may indicate other brine seepage between this location and the road to the north. Called company contact. Hess aware of potential impacts and will be submitting a work plan for delineation and investigation work for this area. Expect early December.

Date: 12/5/2014 **Status:** Awaiting Documentation

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Investigation work plan received this date. Reviewed and approved. Additional area evaluations requested by email response 12/8/2014 from Kris Roberts. See file location.