

Oil Field Environmental Incident Summary

Incident: 20141110174415 **Date/Time of Notice:** 11/10/2014 17:44

Responsible Party: WHITING OIL AND GAS CORPORATION

Well Operator: WHITING OIL AND GAS CORPORATION

Well Name: HANSEN 44-28H CTB

Field Name: SANISH

Well File #:

Date Incident: 11/10/2014 **Time Incident:** 08:30 **Facility ID Number:** 217892-01

County: MOUNTRAIL **Twp:** 153 **Rng:** 92 **Sec:** 28 **Qtr:** SE SE

Location Description:

Submitted By: Brian Wurm

Received By:

Contact Person: Brian Wurm
1700 BROADWAY STE 2300
DENVER, CO 80290

General Land Use: Pasture

Affected Medium: Topsoil

Distance Nearest Occupied Building: 0.3 Mile

Distance Nearest Water Well: 0.3 Mile

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	60	Barrels	60	Barrels	60	barrels

Brine

Other

Description of Other Released Contaminant:

Inspected: **Written Report Received:** 11/27/2015 **Clean Up Concluded:** 11/12/2014

Risk Evaluation:

None noted

Areal Extent:

Light mist over an area approximately 200' by 100' to south of location

Potential Environmental Impacts:

None noted

Action Taken or Planned:

Pipeline was shut in to stop release of fluids. A vac truck was brought in to pick up free liquids and impacted material and impacted material off site will be pushed on site and disposed of.

Wastes Disposal Location: Impacted material will be taken to appropriate disposal.

Agencies Involved:

Updates

Date: 11/13/2014 **Status:** Reviewed - Follow-up Required

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to an on-location valve/piping leak, sprayed off location to the south according to the report. Followup is necessary.

Date: 11/18/2014 **Status:** Inspection

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

11/18/14 - 14:35 on location. The CTB indicated is one of two large production locations that are nearly side by side. The indicated impact area is between the two locations, almost certainly within the same lease block. Inspection of the area shows that there has been significant scraping and grading of the area, and no indication of oil staining remains. No further inspection is necessary in this area.