

Oil Field Environmental Incident Summary

Incident: 20141205081645 **Date/Time of Notice:** 12/05/2014 08:16

Responsible Party: ENDURO OPERATING, LLC

Well Operator: ENDURO OPERATING, LLC

Well Name: HAROLD GRAVSETH 1

Field Name: NORTHEAST LANDA

Well File #: 6285

Date Incident: 12/4/2014 **Time Incident:** 10:00

Facility ID Number:

County: BOTTINEAU

Twp: 164

Rng: 78

Sec: 31

Qtr:

Location Description:

Submitted By: Bryan Pease

Received By:

Contact Person: Bryan Pease
777 MAIN STREET
SUITE 800
FORT WORTH, TX 76102

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: Yes - On Constructed Well Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
--	----------------	--------------	------------------	--------------	-----------------	--------------

Oil

Brine	1.5	Barrels	0.5	Barrels		
--------------	-----	---------	-----	---------	--	--

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

NA

Areal Extent:

Potential Environmental Impacts:

NA

Action Taken or Planned:

Shut valves to stop leak changed out fitting

Wastes Disposal Location: Back in water tank

Agencies Involved:

Updates

Date: 12/5/2014 **Status:** Reviewed - Assigned to Other Agency

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to an on-location valve/piping leak, remained on location according to the report. NDIC retains oversight.