

Oil Field Environmental Incident Summary

Incident: 20141205171830 **Date/Time of Notice:** 12/05/2014 17:18

Responsible Party: SM Energy

Well Operator: SM ENERGY COMPANY

Well Name: JAMES 16X-35HA

Field Name: CAMP

Well File #: 28815

Date Incident: 12/4/2014 **Time Incident:** 07:07

Facility ID Number:

County: MCKENZIE

Twp: 152 **Rng:** 100 **Sec:** 35 **Qtr:** SE SE

Location Description:

Submitted By: John Davies

Received By:

Contact Person: Josh Cook
PO BOX 7168
BILLINGS, MT 59103-7168

General Land Use: Well/Facility Site

Affected Medium: Topsoil

Distance Nearest Occupied Building: 10 Mile

Distance Nearest Water Well:

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: Yes - On Constructed Well Site

Reported to NRC: Unknown

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine						
Other	42	Gallons	42	Gallons		

Description of Other Released Contaminant:

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

Top soil

Areal Extent:

Failure of iron

Potential Environmental Impacts:

Top soil

Action Taken or Planned:

Spill containments under iron so if there is a spill it can be controlled and not contaminate top soil

Wastes Disposal Location: Waste Control Center - Mirror Image

Agencies Involved:

Updates

Date: 12/7/2014 **Status:** Reviewed - Assigned to Other Agency

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to an on-location valve/piping leak, remained on location according to the report. NDIC retains oversight.