

Oil Field Environmental Incident Summary

Incident: 20141218150512 **Date/Time of Notice:** 12/18/2014 15:05

Responsible Party: STATOIL OIL & GAS LP

Well Operator: STATOIL OIL & GAS LP

Well Name: MACMASTER 11-2 1-H

Field Name: BULL BUTTE

Well File #: 19661

Date Incident: 12/17/2014 **Time Incident:** 12:30

Facility ID Number:

County: WILLIAMS

Twp: 156

Rng: 103

Sec: 14

Qtr:

Location Description: All fluids contained on well site.

Submitted By: Jeremy Mohl

Received By:

Contact Person: Jeremy Mohl
6300 BRIDGE POINT PKY, BLDG 2
SUITE 500
AUSTIN, TX 78730

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building: 1 Mile

Distance Nearest Water Well: 1 Mile

Type of Incident: Tank Leak

Release Contained in Dike: Yes - Within Dike

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
--	----------------	--------------	------------------	--------------	-----------------	--------------

Oil

Brine	3	Barrels	3	Barrels		
--------------	----------	----------------	----------	----------------	--	--

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

No immediate risk associated with this incident.

Areal Extent:

All fluids contained within the tank battery containment.

Potential Environmental Impacts:

No potential environmental impacts are associated with this incident.

Action Taken or Planned:

Valve was removed and replaced with a new valve. Continue to monitor valves to minimize any leakage from mechanical failures.

Wastes Disposal Location: Indian Hills Disposal

Agencies Involved:

Updates

Date: 12/19/2014 **Status:** Reviewed - Assigned to Other Agency

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a tank leak, remained on location within the diking according to the report. NDIC retains oversight.