

# Oil Field Environmental Incident Summary

**Incident:** 20141218155632      **Date/Time of Notice:** 12/18/2014 15:56  
**Responsible Party:** BURLINGTON RESOURCES OIL & GAS COMPANY LP  
**Well Operator:** BURLINGTON RESOURCES OIL & GAS COMPANY LP  
**Well Name:** DENALI/NORMAN CTB  
**Field Name:** JOHNSON CORNER      **Well File #:**  
**Date Incident:** 12/17/2014      **Time Incident:** 22:00      **Facility ID Number:** 227059-01  
**County:** MCKENZIE      **Twp:** 150      **Rng:** 96      **Sec:** 4      **Qtr:** LO T3  
**Location Description:**

**Submitted By:** Lewis Schoenberger      **Received By:**  
**Contact Person:** Lewis Schoenberger  
PO BOX 51810  
MIDLAND, TX 79710-1810

**General Land Use:** Well/Facility Site      **Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:** 1 Mile  
**Distance Nearest Water Well:** 1 Mile

**Type of Incident:** Truck Overflow

**Release Contained in Dike:** Yes - On Facility Site      **Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>	2	Barrels				
<b>Brine</b>						
<b>Other</b>						

**Description of Other Released Contaminant:**

**Inspected:**      **Written Report Received:** 8/3/2016      **Clean Up Concluded:** 12/24/2014

**Risk Evaluation:**  
None

**Areal Extent:**  
3 areas on site. One 18 feet by 2 feet. Another 9 feet by 1 foot. A third 38 feet by 14 feet.

**Potential Environmental Impacts:**

None

**Action Taken or Planned:**

The liquid will be collected with a vacuum truck and placed into an appropriate tank on site. The oil impacted solids and debris will be collected for appropriate disposal.

**Wastes Disposal Location:**

**Agencies Involved:**

**Updates**

---

**Date:** 12/19/2014 **Status:** Reviewed - Assigned to Other Agency

**Author:** Roberts, Kris

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Release, due to a truck overflow, remained on location within the diking according to the report. NDIC retains oversight.