

Oil Field Environmental Incident Summary

Incident: 20141222100536 **Date/Time of Notice:** 12/22/2014 10:05

Responsible Party: Enduro Operating

Well Operator: ENDURO OPERATING, LLC

Well Name: Antler Midal Unit CTB

Field Name: ANTLER

Well File #:

Date Incident: 12/20/2014 **Time Incident:** 10:00 **Facility ID Number:** 404995-01

County: BOTTINEAU **Twp:** 163 **Rng:** 82 **Sec:** 25 **Qtr:** NE NE

Location Description: CTB

Submitted By: Bryan Pease

Received By:

Contact Person: Bryan Pease
777 MAIN STREET
SUITE 800
FORT WORTH, TX 76102

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building: 1.5 Mile

Distance Nearest Water Well:

Type of Incident: Tank Overflow

Release Contained in Dike: Yes - On Constructed Well Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	35	Barrels	30	Barrels	30	barrels
Brine	5	Barrels	3	Barrels	3	barrels

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received: 2/26/2015

Clean Up Concluded: 12/22/2014

Risk Evaluation:

NA

Areal Extent:

Potential Environmental Impacts:

NA

Action Taken or Planned:

Replace PLC with relays.

Wastes Disposal Location: Sucked up emulsion and put into tank on location. Finish sucking up emulsion and put into tanks. Contaminated well site gravel will haul to PDI

Agencies Involved:

Updates

Date: 12/22/2014 **Status:** Reviewed - Assigned to Other Agency

Author: Martin, Russell

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to tank overflow, remained on location within the diking according to the report. NDIC retains oversight.