

Oil Field Environmental Incident Summary

Incident: 20150107084039 **Date/Time of Notice:** 01/07/2015 08:40

Responsible Party: Sun Well Services

Well Operator: CONTINENTAL RESOURCES, INC.

Well Name: SKAR 2-28H1

Field Name: STONEVIEW

Well File #: 27868

Date Incident: 1/6/2015 **Time Incident:** 12:00

Facility ID Number:

County: DIVIDE

Twp: 160

Rng: 95

Sec: 28

Qtr:

Location Description:

Submitted By: Timothy Ilse

Received By:

Contact Person: Johnny Knight
201 26th St. E #220
Williston, ND 58801

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Tank Overflow

Release Contained in Dike: Yes - On Facility Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	5	Barrels	5	Barrels	5	barrels
Other						

Description of Other Released Contaminant:

Inspected:

Written Report Received: 10/14/2016

Clean Up Concluded: 1/7/2015

Risk Evaluation:

None

Areal Extent:

20 ft. by 100 ft.

Potential Environmental Impacts:

Well site soil

Action Taken or Planned:

Standing fluid was sucked up and contaminated material will be removed.

Wastes Disposal Location: Production water was taken to SWD and contaminated soil will be taken to Prairie disposal.

Agencies Involved: Called Tom Delling (left voicemail) @ 8:39 am

Updates

Date: 1/7/2015 **Status:** Reviewed - Assigned to Other Agency

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary, this spill remained on location. NDIC retains oversight.