

Oil Field Environmental Incident Summary

Incident: 20150109222948 **Date/Time of Notice:** 01/09/2015 22:29
Responsible Party: MUREX PETROLEUM CORPORATION
Well Operator: MUREX PETROLEUM CORPORATION
Well Name: JOHNSON 24-19
Field Name: NORTH HAAS **Well File #:** 11120
Date Incident: 1/8/2015 **Time Incident:** 02:00 **Facility ID Number:**
County: BOTTINEAU **Twp:** 163 **Rng:** 82 **Sec:** 19 **Qtr:** SW SE
Location Description:

Submitted By: William Jansky **Received By:**
Contact Person: Shannon Holter
363 N. Sam Houston Pkwy. E.
Suite 200
HOUSTON, TX 77060

General Land Use: Pasture **Affected Medium:** Topsoil

Distance Nearest Occupied Building: 1700 Feet

Distance Nearest Water Well:

Type of Incident: Pipeline Leak

Release Contained in Dike: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	15	Barrels	10	Barrels	15	barrels

Brine

Other

Description of Other Released Contaminant:

Inspected: **Written Report Received:** 6/15/2015 **Clean Up Concluded:** 1/30/2015

Risk Evaluation:

Minimal.

Areal Extent:

Effectuated area is approximately 25' x 50'.

Potential Environmental Impacts:

A nearby wetland could be effected.

Action Taken or Planned:

Well was shut in as soon as the stop of production was detected. The surface oil was removed with a hydrovac. As soon as ND One Call is cleared the area will be excavated, contaminated soil removed and flowline replaced. The released is being minimized by current weather conditions.

Wastes Disposal Location: TBD

Agencies Involved: NDHD

Updates

Date: 1/10/2015 **Status:** Reviewed - Follow-up Required

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Pipeline leak near the reported location on property listed as pasture land. Followup is necessary. Possibility of a nearby wetland being affected.

Date: 1/14/2015 **Status:** Inspection

Author: Suess, Bill

Updated Oil Volume: 15.00 barrels

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Work crews had uncovered the pipeline break and determined the horizontal and vertical extent of the impacted area. The impacted area is approximately 50 by 25 feet in size. The impacted area is situated just to the north of a wetland, but release does not appear to have impacted the wetland. Work crews were in the process of excavating impacted soil from the site and will repair the pipeline. Confirmation samples will be collected and a followup report submitted.

Date: 4/27/2015 **Status:** Correspondence

Author: Suess, Bill

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Received confirmation sampling results from Murex. Laboratory data indicates that remediation was successful, and no further action is warranted.