

# Oil Field Environmental Incident Summary

**Incident:** 20150110152148      **Date/Time of Notice:** 01/10/2015 15:21

**Responsible Party:** HESS BAKKEN INVESTMENTS II, LLC

**Well Operator:** HESS BAKKEN INVESTMENTS II, LLC

**Well Name:** TI-ARLENE STONE- 157-95-2419H-2

**Field Name:** TIOGA

**Well File #:** 28723

**Date Incident:** 1/10/2015      **Time Incident:** 08:00

**Facility ID Number:**

**County:** WILLIAMS

**Twp:** 157

**Rng:** 95

**Sec:** 24

**Qtr:**

**Location Description:** TI Alrene Stone 157-95-2419H-2, impacted area released to the south southeast impacting both on and off location.

**Submitted By:** Troy Brunsell

**Received By:**

**Contact Person:** Jason Henry  
1501 MCKINNEY  
HOUSTON, TX 77010

**General Land Use:** Cultivated

**Affected Medium:** Topsoil

**Distance Nearest Occupied Building:** 0.5 Mile

**Distance Nearest Water Well:** 0.5 Mile

**Type of Incident:** Treater Popoff

**Release Contained in Dike:** No

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>						
<b>Brine</b>						
<b>Other</b>	25	Barrels			25	barrels

**Description of Other Released Contaminant:**

Emulsion

**Inspected:**

**Written Report Received:** 2/19/2016

**Clean Up Concluded:** 2/17/2015

**Risk Evaluation:**

Emulsion mist off location to the south southeast impacting snow / topsoil

**Areal Extent:**

Approx. 75ft x 300ft

**Potential Environmental Impacts:**

Topsoil

**Action Taken or Planned:**

Location shut in for Maint Dept. to conduct repair. Cleanup crew will be dispatched to cleanup the the impacted area.

**Wastes Disposal Location:** Approved waste facility

**Agencies Involved:**

**Updates**

---

**Date:** 1/10/2015    **Status:** Reviewed - Follow-up Required

**Author:** Roberts, Kris

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Off-site spray due to a treater popoff valve release. Sprayed off the south-southeast portion of the pad on to soil and snow. Followup is necessary. Site will be visited on Monday 1/12/15.

---

**Date:** 2/3/2015    **Status:** Inspection

**Author:** Stockdill, Scott

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Arrived on location 2/3/2015 16:07.

Impacted area scraped up with impacted material being staked off location.

More followup is necessary to ensure cleanup.

---

**Date:** 4/13/2015    **Status:** Inspection

**Author:** Stockdill, Scott

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Arrived on location 14:18 4/9/2015.

No residual sign of spill at location.

Request cleanup confirmation samples from company.

---

**Date:** 12/6/2016    **Status:** Correspondence

**Author:** O'Gorman, Brian

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Received an email from Hess's Environmental consultant with a Site Assessment Work Plan (SAWP). SAWP recommends further delineation of the release area due to exceedences of EC and Total Petroleum Hydrocarbons (TPH) from confirmation samples. Report added to incident folder. Further followup needed.